Pre-Purchase Inspection				عد	sic	- Autom	סר	bilia	•										
Report No		_			04	25 250 61	3			Auction Lot No									
			Main	itenai		Modifications &		oration	s	16									
		ABN:	95 933	3 498	/16			MVRL 38											
Inspection Date					Make/N	lodel		Year	Odometer - MIs / Km	VIN		R	ating	/5	4.0				
45408			B	Bentley	Brook	lands R LWB		1998	169,341km	SCB2F20C2WCH6640		All values will be rounded down to the nearest 0.5							
		Ove	erall Ra	ting				Сс	mments										
	1	1	1	1	0	Wor	derful	luxurv veh	icle that needs	some work.									
	-	-	-	-	U										_				
EXTERIOR	Good	Fair	Repair	N/C	N/A			C	omments			Туј	pe 'a'	for t	icks				
Presentation	~														_				
Glass	~																		
Bodywork																			
Paintwork						Scrape on R/H/R wheel a	rch. Seve	eral scratche	es and marks.										
Lamps Condition Bumper Bars	✓		-			R/H/R of bar scrapped.													
Brightwork	~		-			ing ing is on bar scrapped.													
Seals	-																		
Convertible Roof					~														
INTERIOR	Good	Fair	Repair	N/C	N/A			C	omments										
Boot Area	✓																		
Seats & Belts	~		~			Electric seats N/W.													
Floor Coverings	~																		
Headlining/Visors	~																		
Trim	~					Some wood grain starting	to crac	k.											
Doors	~																		
Windows and Mirrors	~																		
Heating and Ventilation			✓			Air conditioning N/W.													
Lights/Wipers/Washers/Horn	~																		
Other Electrical			~			Engine check lamp on. So	me elec	ctrical anom	olies.										
Entertainment Equipment																			
		F air	Demoir	N//0					omments										
UNDERBODY Structure	Good	Fair	Repair	N/C	N/A														
Corrosion																			
Powertrain	~																		
Exhaust	✓																		
Brakes	 ✓ 		~			Hand brake travel excessi	ve.												
Wheels & Tyres			~			Front tyres U/S and rears													
Steering & Suspension		✓				Front ride height appears	low.												
Fuel System																			
Fluid Leaks	✓					Engine and transmission	sumps w	vet.		Dec 1/2									
										Pge 1/2									
	Good	Fair	Poncia	N/C	N/A				omments										
Presentation	9000		Repair	N/C	N/A	Evidence of rat activity.		C											
Fluid Levels/Condition	~	~				LVIGENCE OF TAL ACLIVILY.													
Cooling System																			
Power Steering	v																		
Electrical	v																		
Engine Running	~																		
Air Conditioning			~			N/W.													
	Good	Fair	Repair	N/C	N/A			C	omments										
RUAD IESI	~																		
Engine Performance	•																		
Engine Performance Transmission	 ✓ ✓ 					1							1						
Engine Performance Transmission Noise and Vibration Steering and Suspension	v																		
Engine Performance Transmission Noise and Vibration Steering and Suspension Braking	~																		
Engine Performance Transmission Noise and Vibration Steering and Suspension Braking Clutch	 ✓ ✓ ✓ 				~														
ROAD TEST Engine Performance Transmission Noise and Vibration Steering and Suspension Braking Clutch Instruments	v				~														

							Кеу													
Good																				
Fair	Comme	ensurate f	for age o	of vehic	cle but h	ias wear	and te	ar					N/S	N	ot secure					
Repair	Require	es repair,	replace	ment o	r refurb	ishment							N/W	N	ot working					
Wetting	Fluid escaping with the potential to drip												N/A	N	ot Applicable	ĺ				
	Fluid e	scaping a	nd dripp	oing									N/C	N	ot checked					
$- \bigstar \bigstar & \updownarrow & \swarrow & & \\ - \bigstar & \bigstar & \bigstar & & & \\ - \bigstar & \bigstar & & & & & & \\ \end{array}$	Vehicle requires substantial work or restoration																			
	$7 \star \star \star$																			
	Vehicle	is in very	v good c	onditio	n															
	Image: Selection is the ison interstrate with age and useable Image: Vehicle is in very good condition Vehicle is in excellent condition																			
						Di	eclaim	or												
	Disclaimer This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																			
Classic Automobilia (MVRL382	Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.											influence to your decision to								
The following items are not i	ne following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanica components.											or any internal mechanical								
This pre-purchase inspection	report is	not a sub	ostitute	for a ro	adwort	hy certif	icate ar	nd in no	way im	nplies	s the vel	hicle	will or will no	t pas	s a roadworthy inspection.					
															Pge 2/2					
										_	_						 	 		

										(

##