

Pre-Purchase Inspection		<div style="border: 2px solid black; padding: 5px; text-align: center;"> Classic Automobilia 0425 250 613 Maintenance, Modifications & Restorations </div>				Auction Lot No	
Report No						15	
		ABN: 95 933 498 716		MVRL 38236			
Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN			
45406	Bentley Mulsanne S	1987	187,480mls	SCBZN00A5JCH22247			
Overall Rating		Comments					
1	1	1	0	0	Solid vehicle that has slipped into disrepair.		
EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments	
Presentation		✓					
Glass	✓						
Bodywork	✓					Spoiler damaged.	
Paintwork			✓			Large cracks and imperfections in roof and rear window surround. Paint dull. Blister in R/H/F guard	
Lamps Condition	✓						
Bumper Bars	✓						
Brightwork		✓					
Seals		✓					
Convertible Roof			✓			Sunroof N/W.	
INTERIOR	Good	Fair	Repair	N/C	N/A	Comments	
Boot Area		✓					
Seats & Belts		✓				Aged and worn.	
Floor Coverings	✓						
Headlining/Visors	✓						
Trim		✓				Aged and soiled. Centre console woodgrain cracked.	
Doors	✓						
Windows and Mirrors			✓			Poor window operation and some switches N/W. Drivers electric mirror N/W.	
Heating and Ventilation	✓						
Lights/Wipers/Washers/Horn	✓						
Other Electrical			✓			Electric seats N/W.	
Entertainment Equipment		✓				Aerial broken.	
ABS/SRS	✓						
UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments	
Structure	✓						
Corrosion	✓						
Powertrain	✓						
Exhaust	✓						
Brakes	✓						
Wheels & Tyres		✓					
Steering & Suspension	✓						
Fuel System			✓			Fuel delivery lean, suspect warm up regulator faulty.	
Fluid Leaks			✓			Engine, transmission and power steering leaks.	
Page 1/2							
ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments	
Presentation	✓						
Fluid Levels/Condition	✓					Coolant level lamp on but level OK.	
Cooling System		✓				Slow to get to temperature.	
Power Steering	✓						
Electrical	✓						
Engine Running			✓			Difficult to start and runs rough. (see fuel system remarks)	
Air Conditioning	✓						
ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments	
Engine Performance			✓			Lacks power due to fuel injection problem.	
Transmission							
Noise and Vibration							
Steering and Suspension							
Braking							
Clutch							
Instruments							
General Comments							

Rating /5 **3.0**
 All values will be rounded down to the nearest 0.5

Type 'a' for ticks

--

Key

Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
★ ☆ ☆ ☆ ☆	Fluid escaping and dripping	N/C	Not checked
★ ★ ☆ ☆ ☆	Vehicle requires substantial work or restoration		
★ ★ ★ ☆ ☆	Vehicle is in poor condition and in need of TLC		
★ ★ ★ ★ ☆	Vehicle is commensurate with age and useable		
★ ★ ★ ★ ★	Vehicle is in very good condition		
	Vehicle is in excellent condition		

Disclaimer

This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.

Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.

This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.