Pre-Purchase Inspection			Classic Automobilia															
Report No					04	25 250	613	3			Auction Lot No							
			Main	tenar	nce, I	Modificatio	ns & I	Resto	ration	s	13							
		A D NI	95 933	100	716				M//DL 20	226								
		ADIN.	33 333	436	/10			MVRL 38236										
Inspection Date				N	Make/N	lodel			Year	Odometer - Mls / Km	VIN			R	ating /	/ 5	4.0	
45406				Cate	erham	Super 7			1983	2,149km	CS33814							
														All values w	iii be round	eu down to	ine nearest o.s	,
		Ove	rall Ra	ting					Co	mments								
	1	1	1	1	0			Lots of	f fun, nee	eds finishing to	uches.							
EVTEDIOD				N/0	N/4								T	اداد				
EXTERIOR	Good	Fair	Repair	N/C	N/A				Co	omments				ıyp	e a	tor τι	CKS	
Presentation	~													_				
Glass					V													
Bodywork	V																	
Paintwork	V																	
Lamps Condition	~																	
Bumper Bars Brightwork																		
Brightwork																		
Seals Convertible Roof																		
INTERIOR	Good	Fair	Repair	N/C					0	ommente								
Boot Area	Joou	ı all	. iopaii	14/0					C									
Seats & Belts	~				•													
Floor Coverings	V																	
Headlining/Visors	V				J													
Trim		>			•													
Doors																		
Windows and Mirrors			~		ľ	Mirror N/S.												
Heating and Ventilation			·		_	,												
Lights/Wipers/Washers/Horn	~				·													
Other Electrical		~				Poor wiring.												
Entertainment Equipment					~													
ABS/SRS					✓													
UNDERBODY	Good	Fair	Repair	N/C	N/A				Co	omments								
Structure	✓																	
Corrosion	✓																	
Powertrain	✓																	
Exhaust	~																	
Brakes	V																	
Wheels & Tyres	~																	
Steering & Suspension	,		~			L/H/F shock abso	rber leaki	ing.										
Fuel System Fluid Leaks	*					Final drive and o												
Fluid Leaks		V			Cate Max Camments Camment													
											LRC 1/2							
ENOINE DAY	0	F-·	Do-	NI/O	AI/A													
ENGINE BAY	Good	Fair	Repair	N/C	N/A				Co	mments								
Presentation Fluid Lovels/Condition	, ,	V		Comments														
Fluid Levels/Condition Cooling System	Y					DI ake IIUIQ resevo	ıı perishi	eu.										
Cooling System Power Steering	~																	
Power Steering Electrical		>			*													
Engine Running	~	▼																
Air Conditioning	•				V													
ROAD TEST	Good	Fair	Repair	N/C					Co	omments								
Engine Performance	✓	-		-														
Transmission	•																	
Noise and Vibration	•	>																
Steering and Suspension	~																	
Braking	→													1				
Clutch	•					Clutch master cyl	inder leal	king.										
Instruments	✓																	
												_						
						General Comme	ents											

						Key										
Good Operational or well presented at time of inspection Fair Commensurate for age of vehicle but has wear and tear Repair Requires repair, replacement or refurbishment Wetting Fluid escaping with the potential to drip Fluid escaping and dripping										U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked					
★ ☆ ☆ ☆ ★ ★ ☆ ☆ ★ ★ ★ ☆	Vehicle is in Vehicle is c	Vehicle requires substantial work or restoration Vehicle is in poor condition and in need of TLC Vehicle is commensurate with age and useable Vehicle is in very good condition Vehicle is in excellent condition														
nis is a visual inspection only o					8236). No		onents a					been				
Classic Automobilia (MVRL382	236) will not b	oe held liable	e or resp	onsible i	n regard: purchase Engine	s to any	claim(s) hicle.) in rela	tion	to this report or any impl						
This pre-purchase inspection	n report is not	t a substitute	e for a ro	adworth	ny certific	cate and	d in no w	vay imp	lies t	he vehicle will or will not	pass a roadworthy inspectio	n.				