					_												
Pre-Purchase Inspection		-		959	SSIC AUtomobilia												
Report No			0425 250 613 Aucti							Auction Lot No							
			Maint	tenar	ice, I	Modifications &	z Resto	oration	S	20							
			05.022	400	74.6												
		ABN:	95 933	498	116			MVKL 38	236								
Inspection Date				N	/lake/M	lodel		Year	Odometer - Mls / Km	VIN			Ra	ating /	' 5	2.5	
45406				Chrys	sler Cha	arger 770		1972		VH8H29CB110966							
												,	All values w	iii be rounde	ed down to ti	ne nearest 0.5	
		Ove	rall Rat	ting	l			Co	mments								
	1	1	0.5	0	0		So	olid vehicl	e in need of TL	C.							
EXTERIOR	Good	Fair	Repair	N/C	N/A			C	omments				Тур	e 'a' '	for tic	cks	
Presentation		✓															
Glass	✓												ı				
Bodywork		✓				Vinyl trim peeling.											
Paintwork		~															
Lamps Condition		✓				Fog lamps rusty.											
Bumper Bars	✓					Tarnished.											
Brightwork		✓															
Seals		✓															
Convertible Roof					✓												
INTERIOR	Good	Fair	Repair	N/C	N/A			C	omments								
Boot Area		~			77.15 AVAILABERT OF COMMONTS VIN Rating /5 2.5												
Seats & Belts			✓			Torn and soiled											
Floor Coverings			✓														
Headlining/Visors			✓			Torn and soiled.											
Trim			✓			Rear panels missing torn	n and tatty	<i>'</i> .									
Doors			✓			L/h door rusted at base.	Pass exte	rior door h	andle broken.								
Windows and Mirrors		✓															
Heating and Ventilation			✓			Disconnected and only of	one fan sp	eed.									
Lights/Wipers/Washers/Horn		✓				Horn poor washers N/W	<i>l</i> .										
Other Electrical				✓													
Entertainment Equipment			✓			N/W.											
ABS/SRS					✓												
UNDERBODY	Good	Fair	Repair	N/C	N/A			C	omments								
Structure	✓																
Corrosion	✓					Rust repair panel on R/H	H/F sill.										
Powertrain	✓																
Exhaust		~															
Brakes		~															
Wheels & Tyres		~															
Steering & Suspension		V															
Fuel System		V															
Fluid Leaks		~				Engine and transmission											
										Pge 1/2							
ENGINE BAY	Good	Fair	Repair	N/C	N/A			C	omments								
Presentation		✓															
Fluid Levels/Condition		~															
Cooling System	✓																
Power Steering					~												
Electrical		✓															
Engine Running	✓																
Air Conditioning					~												
ROAD TEST	Good	Fair	Repair	N/C	N/A			Ce	omments								
Engine Performance	✓																
Transmission	✓					Selector not aligned.											
Noise and Vibration	✓																
Steering and Suspension	✓																
Braking	✓																
Clutch					~												
Instruments		✓				Aged, fuel gauge N/W.											
						0											
						General Comments											

						Key										
Good Fair Repair Wetting	Fair Commensurate for age of vehicle but has wear and tear Repair Requires repair, replacement or refurbishment Wetting Fluid escaping with the potential to drip Fluid escaping and dripping										Unservicable Not secure Not working Not Applicable Not checked					
★ ☆ ☆ ☆ ★ ★ ☆ ☆ ★ ★ ★ ☆	Vehicle is in Vehicle is c	Vehicle requires substantial work or restoration Vehicle is in poor condition and in need of TLC Vehicle is commensurate with age and useable Vehicle is in very good condition Vehicle is in excellent condition														
nis is a visual inspection only o					8236). No		onents a					been				
Classic Automobilia (MVRL382	236) will not b	oe held liable	e or resp	onsible i	n regard: purchase Engine	s to any	claim(s) hicle.) in rela	tion	to this report or any impl						
This pre-purchase inspection	This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.															