			1	1									
Pre-Purchase Inspection			Clc	35	sic	= Automobilia							
Report No					04	Auction Lot No							
· · · · · · · · · · · · · · · · · · ·		- <b>  </b>	Main	tenai		Modifications & Restorations 17							
			05.033	2 400	71.0								
		ABN:	95 933	3 498	/16	MVRL 38236							
Inspection Date				1	Make/N	Model Year Odometer - Win Wis / Km	Rat	ting /5	<mark>5.0</mark>				
45408				Lanci	a Aure	lia B20 GT 1957 82,854mls B203886	All values will be rounded down to the nearest 0.5						
		0	well De	A!			7 III Valdes Will	be rounded down to the h	icurest 0.5				
			erall Ra		_	Comments							
	1	1	1	1	1	Very nice restoration.							
EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments	Type	e 'a' for tick	/C				
Presentation	<b>✓</b>		- topan		1071		Турс	a loi ticr	.5				
Glass	-												
Bodywork	-												
, Paintwork	<b>~</b>					Some blemishes and a little flat.							
Lamps Condition	<b>✓</b>												
Bumper Bars	~												
Brightwork	<b>✓</b>					Some tarnishing.							
Seals	~												
Convertible Roof					~								
INTERIOR	Good	Fair	Repair	N/C	N/A	Comments							
Boot Area	~												
Seats & Belts	~												
Floor Coverings	<b>✓</b>												
Headlining/Visors	~												
Trim	~												
Doors	~												
Windows and Mirrors	~												
Heating and Ventilation			~			N/W.							
Lights/Wipers/Washers/Horn	<b>~</b>												
Other Electrical				<b>V</b>	. 4								
Entertainment Equipment  ABS/SRS					<b>Y</b>								
UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments							
Structure	<b>✓</b>		. ropum		1071	Evidence of repairs to underbody.							
Corrosion	~												
Powertrain	~												
Exhaust	~												
Brakes	~												
Wheels & Tyres	~												
Steering & Suspension			~			Excessive play in steering.							
Fuel System	<b>V</b>												
Fluid Leaks	<b>~</b>												
						Pge 1/2							
		_											
ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments							
Presentation	<b>✓</b>												
Fluid Levels/Condition	<b>✓</b>					De dieten leeking							
Cooling System			<b>~</b>		.4	Radiator leaking.							
Dower Charin-					<b>V</b>								
Power Steering													
Electrical	<b>Y</b>												
Electrical Engine Running	<b>y</b>												
Electrical Engine Running Air Conditioning		Fair	Repair	N/C	V N/A	Comments							
Electrical Engine Running Air Conditioning ROAD TEST	Good	Fair	Repair	N/C		Comments Throttle sticks.							
Electrical Engine Running Air Conditioning	•	Fair	Repair	N/C									
Electrical Engine Running Air Conditioning  ROAD TEST  Engine Performance  Transmission	Good	Fair	Repair	N/C									
Electrical Engine Running Air Conditioning  ROAD TEST  Engine Performance	Good	Fair		N/C		Throttle sticks.							
Electrical Engine Running Air Conditioning  ROAD TEST  Engine Performance  Transmission  Noise and Vibration  Steering and Suspension	Good	Fair	<b>✓</b>	N/C		Throttle sticks.  Severe vibration in front end.							
Electrical Engine Running Air Conditioning  ROAD TEST  Engine Performance  Transmission  Noise and Vibration  Steering and Suspension  Braking	Good	Fair	<b>✓</b>	N/C		Throttle sticks.  Severe vibration in front end.							
Electrical Engine Running Air Conditioning  ROAD TEST  Engine Performance  Transmission  Noise and Vibration	Good	Fair	<b>✓</b>	N/C	N/A	Throttle sticks.  Severe vibration in front end.							
Electrical Engine Running Air Conditioning  ROAD TEST  Engine Performance  Transmission  Noise and Vibration  Steering and Suspension  Braking  Clutch	Good	Fair	<b>✓</b>	N/C	N/A	Throttle sticks.  Severe vibration in front end.  Steering needs attention.							

						Key									
Good Fair Repair Wetting	Good Operational or well presented at time of inspection  Fair Commensurate for age of vehicle but has wear and tear  Repair Requires repair, replacement or refurbishment  Wetting Fluid escaping with the potential to drip  Fluid escaping and dripping									U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked				
★ ☆ ☆ ☆         ★ ★ ☆ ☆         ★ ★ ★ ☆	Vehicle requires substantial work or restoration  Vehicle is in poor condition and in need of TLC  Vehicle is commensurate with age and useable  Vehicle is in very good condition  Vehicle is in excellent condition														
nis is a visual inspection only o					8236). No		onents a					been			
Classic Automobilia (MVRL382	236) will not b	oe held liable	e or resp	onsible i	n regard: purchase <b>Engine</b>	s to any	claim(s) hicle.	) in rela	tion	to this report or any impl					
This pre-purchase inspection	n report is not	t a substitute	e for a ro	adworth	ny certific	cate and	d in no w	vay imp	lies t	he vehicle will or will not	pass a roadworthy inspectio	n.			