































Pre-Purchase Inspection		<div>Classic Automobilia</div> <div>0425 250 613</div> <div>Maintenance, Modifications & Restorations</div>					Auction Lot No		
Report No							2		
		ABN: 95 933 498 716			MVRL 38236				
Inspection Date		Make/Model				Year	Odometer - Mls / Km	VIN	
45810		MGA				1962	76,859mls	MGA641108050	
		Overall Rating				Comments			
		1	1	1	0	0	Mechanically sound with excellent structure.		
EXTERIOR		Good	Fair	Repair	N/C	N/A	Comments		
Presentation			✓						
Glass			✓				Stone chip in windscreen.		
Bodywork			✓				Poor panel fit and finish. Most panels deformed.		
Paintwork				✓			Paint is cracked, peeling and flat - damage around filler cap from overflow.		
Lamps Condition			✓						
Bumper Bars			✓				Poor chrome with some surface rust evident.		
Brightwork			✓				Boot lid MGA badge broken.		
Seals			✓						
Convertible Roof			✓						
INTERIOR		Good	Fair	Repair	N/C	N/A	Comments		
Boot Area			✓						
Seats & Belts				✓			Seat belt is poorly mounted and needs attention.		
Floor Coverings			✓						
Headlining/Visors						✓			
Trim			✓				Aged and untidy.		
Doors			✓						
Windows and Mirrors				✓			Mirrors poor.		
Heating and Ventilation						✓			
Lights/Wipers/Washers/Horn				✓			Headlamp N/W, Indicators N/W. headlamp switch broken.		
Other Electrical						✓			
Entertainment Equipment				✓			N/W.		
ABS/SRS						✓			
UNDERBODY		Good	Fair	Repair	N/C	N/A	Comments		
Structure		✓							
Corrosion		✓							
Powertrain		✓							
Exhaust				✓			U/S.		
Brakes			✓						
Wheels & Tyres				✓			Tyres aged and cracking.		
Steering & Suspension			✓				Aged and worn.		
Fuel System			✓						
Fluid Leaks			✓						
							Pge 1/2		
ENGINE BAY		Good	Fair	Repair	N/C	N/A	Comments		
Presentation			✓						
Fluid Levels/Condition		✓							
Cooling System		✓							
Power Steering						✓			
Electrical			✓						
Engine Running		✓							
Air Conditioning						✓			
ROAD TEST		Good	Fair	Repair	N/C	N/A	Comments		
Engine Performance		✓							
Transmission		✓							
Noise and Vibration			✓						
Steering and Suspension			✓						
Braking			✓						
Clutch		✓							
Instruments			✓				Aged and tatty.		
General Comments									

Key																					
Good		Operational or well presented at time of inspection						U/S		Unservicable											
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure											
Repair		Requires repair, replacement or refurbishment						N/W		Not working											
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable											
    		Fluid escaping and dripping						N/C		Not checked											
    		Vehicle requires substantial work or restoration																			
    		Vehicle is in poor condition and in need of TLC																			
    		Vehicle is commensurate with age and useable																			
    		Vehicle is in very good condition																			
    		Vehicle is in excellent condition																			
Disclaimer																					
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																					
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																					
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																					
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																					
Page 2/2																					