































Pre-Purchase Inspection		<div>Classic Automobilia</div> <div>0425 250 613</div> <div>Maintenance, Modifications &amp; Restorations</div>					Auction Lot No			
Report No							Lot 27			
		ABN: 95 933 498 716			MVRL 38236					
Inspection Date	Make/Model				Year	Odometer - Mls / Km	VIN	Rating /5	2.5	
30/7/24	Jaguar XK150				1959	31,264mls	S8249990N	All values will be rounded down to the nearest 0.5		
		Overall Rating				Comments				
		1	1	0.5	0	0	Good car, solid base for restoration.			
EXTERIOR		Good	Fair	Repair	N/C	N/A	Comments			
Presentation			✓							
Glass		✓								
Bodywork			✓				Driver's door fit poor. General panel fit poor and cracking filler in areas.			
Paintwork				✓			Aged.			
Lamps Condition		✓								
Bumper Bars		✓								
Brightwork			✓							
Seals				✓						
Convertible Roof						✓				
INTERIOR		Good	Fair	Repair	N/C	N/A	Comments			
Boot Area			✓				Aged.			
Seats & Belts			✓							
Floor Coverings			✓							
Headlining/Visors			✓							
Trim			✓				Aged and untidy.			
Doors			✓							
Windows and Mirrors		✓								
Heating and Ventilation				✓			Fan noisy and heater N/W.			
Lights/Wipers/Washers/Horn				✓			Poor sweep and operation. Several lights N/W.			
Other Electrical				✓						
Entertainment Equipment						✓				
ABS/SRS						✓				
UNDERBODY		Good	Fair	Repair	N/C	N/A	Comments			
Structure		✓								
Corrosion			✓				Some corrosion evident in outer underbody.			
Powertrain			✓				Mounts perished. Univeral joints worn.			
Exhaust				✓			Unserviceable, unsecure and hits underbody components.			
Brakes				✓			Aged and calipers leaking.			
Wheels & Tyres			✓							
Steering & Suspension				✓			Aged, worn and perished.			
Fuel System				✓			Fuel tank badly dented and has had several repairs.			
Fluid Leaks				✓			Final drive and transmission leaking badly. Engine wet. Rusty coolant stains on engine pipes.			
										Pge 1/2
ENGINE BAY		Good	Fair	Repair	N/C	N/A	Comments			
Presentation			✓							
Fluid Levels/Condition		✓								
Cooling System			✓				Coolant rusty.			
Power Steering						✓				
Electrical			✓							
Engine Running			✓				Idles harshly and throttle sticks.			
Air Conditioning						✓				
ROAD TEST		Good	Fair	Repair	N/C	N/A	Comments			
Engine Performance		✓								
Transmission			✓				Gears crunch when cold. Overdrive not checked.			
Noise and Vibration			✓							
Steering and Suspension			✓							
Braking				✓			Poor performance and excessive pedal travel. Hand brake poor.			
Clutch			✓							
Instruments			✓				Clock N/W.			
General Comments										

Key																						
Good		Operational or well presented at time of inspection						U/S		Unservicable												
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure												
Repair		Requires repair, replacement or refurbishment						N/W		Not working												
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable												
    		Fluid escaping and dripping						N/C		Not checked												
    		Vehicle requires substantial work or restoration																				
    		Vehicle is in poor condition and in need of TLC																				
    		Vehicle is commensurate with age and useable																				
    		Vehicle is in very good condition																				
    		Vehicle is in excellent condition																				
Disclaimer																						
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																						
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																						
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																						
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																						
Page 2/2																						