

Pre-Purchase Inspection

Report No

Classic Automobilia

0425 250 613

Maintenance, Modifications & Restorations

Auction Lot No

ABN: 95 933 498 716

MVRL 38236

Inspection Date

4/3/25

Make/Model

Porsche 996 Turbo

Year

2003

Odometer - Mls / Km

145,082km

VIN

WPOZZZ99Z3S680867

Rating /5

4.5

All values will be rounded down to the nearest 0.5

Overall Rating

11110.5

Comments

Excellent vehicle.

EXTERIOR

GoodFairRepairN/CN/A

Comments

Presentation

✓

Glass

✓

Bodywork

✓

Paintwork

✓

Some small marks.

Lamps Condition

✓

Bumper Bars

✓

Front bar cracked, scuffed and scraped on underside but new lip spoiler. Rear bar has minor scuffs

Brightwork

✓

Seals

✓

Convertible Roof

✓

Sunroof.

INTERIOR

GoodFairRepairN/CN/A

Comments

Boot Area

✓

✓

Frunk lid struts U/S.

Seats & Belts

✓

Drivers seat a little aged.

Floor Coverings

✓

Headlining/Visors

✓

Trim

✓

Plastics have scratches.

Doors

✓

Driver's door grab area badly scratched.

Windows and Mirrors

✓

Heating and Ventilation

✓

A/con not working.

Lights/Wipers/Washers/Horn

✓

Other Electrical

✓

Entertainment Equipment

✓

ABS/SRS

✓

UNDERBODY

GoodFairRepairN/CN/A

Comments

Structure

✓

Corrosion

✓

Powertrain

✓

Exhaust

✓

Brakes

✓

Wheels & Tyres

✓

Wheels badly chipped. Rear tyres 11 years old. Front tyres 8 Y/O.

Steering & Suspension

✓

R/H/F shock leaking. F shocks impacting aftermarket sway bar links.

Fuel System

✓

Fluid Leaks

✓

L/H turbo drain leaking. Transmission wiring wicking oil.

ENGINE BAY

GoodFairRepairN/CN/A

Comments

Presentation

✓

Fluid Levels/Condition

✓

Cooling System

✓

Power Steering

✓

Electrical

✓

Engine Running

✓

Air Conditioning

✓

Compressor not engaging.

ROAD TEST

GoodFairRepairN/CN/A

Comments

Engine Performance

✓

Transmission

✓

Noise and Vibration

✓

Steering and Suspension

✓

Braking

✓

Clutch

✓

Instruments































✓

General Comments

Type 'a' for ticks

Pge 1/2

1

Key																						
Good		Operational or well presented at time of inspection						U/S		Unservicable												
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure												
Repair		Requires repair, replacement or refurbishment						N/W		Not working												
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable												
    		Fluid escaping and dripping						N/C		Not checked												
    		Vehicle requires substantial work or restoration																				
    		Vehicle is in poor condition and in need of TLC																				
    		Vehicle is commensurate with age and useable																				
    		Vehicle is in very good condition																				
    		Vehicle is in excellent condition																				
Disclaimer																						
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																						
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																						
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																						
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																						
Page 2/2																						