Pre-Purchase Inspection			⊂lc	3 59	sic	Automobilia							
Report No					04	25 250 613	Auction Lot No						
			Main	itenar		Addifications & Restorations							
		ABN:	95 93 3	3 498 7	716	MVRL 38236							
Inspection Date				N	/lake/M	odel Year Odometer - Mis / Km	VIN		Rating /	' 5	3.5		
45919				Ве	ntley T	urbo R 1986 45,102mls	H14213						
									All values will be rounde	ed down to the	nearest 0.5		
		Ove	erall Ra			Comments							
	1	1	1	0.5	0	Solid and mechanically good but ag	ged.						
EVTEDIOD	Good	Fair	Popoir	N/C	N/A	Comments			Type 'e'	for tic	ke		
Presentation	Good		Repair	IVC	IVA	Comments			Type 'a'	ioi tic	KS		
Glass		Y											
Bodywork		V				Small dent R/H/R door. L/H/F wheel arch damaged.							
Paintwork		V				Poor paint with cracking and fading.							
amps Condition		•											
sumper Bars		•											
rightwork		✓											
seals		~											
Convertible Roof					✓								
NTERIOR	Good	Fair	Repair	N/C	N/A	Comments							
Boot Area	✓												
Seats & Belts		✓											
loor Coverings		✓											
leadlining/Visors		✓											
rim		✓				Woodwork cracking. Dash top poor. Aged.							
oors .			~			L/H/R door/window frame N/S.							
Vindows and Mirrors	✓												
leating and Ventilation			~			A/con not cold.							
ights/Wipers/Washers/Horn	~												
Other Electrical	~												
Entertainment Equipment		~											
ABS/SRS					V								
JNDERBODY	Good	Fair	Repair	N/C	N/A	Comments							
Structure Corrosion	>												
Powertrain	V												
Exhaust		✓											
Brakes	✓												
Wheels & Tyres		✓											
Steering & Suspension		✓				L/H/R level shock leaking.							
Fuel System			~			Fuel leak from fuel pump.							
Fluid Leaks		~				Driveline is generally wet.							
							Pge 1/2						
ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments							
resentation	✓												
luid Levels/Condition		~				Hydralic fluid low.							
cooling System													
ower Steering	Y												
ngine Running	>												
ir Conditioning	V		~			Not cold.							
ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments							
ngine Performance	G00d ✓	. un	opan			Comments							
ransmission	y												
oise and Vibration													
teering and Suspension	V												
raking	V												
					✓								
lutch		l		1	l			-					
lutch nstruments	✓												
	✓												

						Key												
Good Fair Repair Wetting	Fair Commensurate for age of vehicle but has wear and tear Repair Requires repair, replacement or refurbishment Fluid escaping with the potential to drip												No No	nservicable ot secure ot working ot Applicable ot checked				
★ ★ ☆ ☆ ☆ ★ ★ ☆ ☆ ★ ★ ★ ☆	Vehicle is Vehicle is	Vehicle requires substantial work or restoration Vehicle is in poor condition and in need of TLC Vehicle is commensurate with age and useable Vehicle is in very good condition																
Vehicle is in excellent condition Disclaimer This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been																		
conclusively diagnosed. Classic Automobilia (MVRL38 ne following items are not	236) will not	be held liab	ole or resp	onsible i	n regard: purchase Engine	s to any	v claim(s hicle. ression	s) in rela	ition	to this r	eport (or any impl	lied i					
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																		
														rge 2/2				