

Observation Report		Classic Automobilia 0425 250 613 Maintenance, Modifications & Restorations					Auction Lot No	
Report No								
		ABN: 95 933 498 716					MVRL 38236	
Inspection Date	Make/Model					Year	Odometer - Mls / Km	VIN
46069	BMW 323 JPS					1981	182,144km	WBAAH3206B7253181
		Overall Rating					Comments	
		1	1	1	0.5	0	Good vehicle that needs some finishing work.	
EXTERIOR		Good	Fair	Repair	N/C	N/A	Comments	
Presentation		✓						
Glass		✓						
Bodywork		✓					Front & rear valances misaligned. Front wheel arch inner guards missing. L/H front guard n/s.	
Paintwork		✓					Some marks and scratches.	
Lamps Condition			✓				Rear lamp poor fit due to new rubbers and body holders welded in.	
Bumper Bars			✓				Front bar/valance n/s and has a couple of dents.	
Brightwork						✓		
Seals			✓					
Convertible Roof						✓		
INTERIOR		Good	Fair	Repair	N/C	N/A	Comments	
Boot Area			✓					
Seats & Belts				✓			Seat belts aged and not retracting.	
Floor Coverings			✓					
Headlining/Visors		✓						
Trim			✓					
Doors			✓				Door trims and and handles aged and worn.	
Windows and Mirrors			✓					
Heating and Ventilation			✓				Vent controls have been closed off.	
Lights/Wipers/Washers/Horn		✓					Wipers slow.	
Other Electrical			✓					
Entertainment Equipment		✓						
ABS/SRS						✓		
UNDERBODY		Good	Fair	Repair	N/C	N/A	Comments	
Structure			✓				Front floors and rails distorted. Sill lips damaged and distorted, some surface rust.	
Corrosion			✓				Rust in R/H boot well and small hole in passenger floor.	
Powertrain		✓					Gear selector bracket not secure.	
Exhaust		✓						
Brakes		✓						
Wheels & Tyres		✓						
Steering & Suspension		✓						
Fuel System				✓			Fuel filter not secure, low pressure piping and filter used instead of high pressure fittings.	
Fluid Leaks								
							Pge 1/2	
ENGINE BAY		Good	Fair	Repair	N/C	N/A	Comments	
Presentation								
Fluid Levels/Condition								
Cooling System								
Power Steering								
Electrical								
Engine Running								
Air Conditioning								
ROAD TEST		Good	Fair	Repair	N/C	N/A	Comments	
Engine Performance								
Transmission								
Noise and Vibration								
Steering and Suspension								
Braking								
Clutch								
Instruments								
General Comments								

Key																						
Good		Operational or well presented at time of inspection						U/S		Unservicable												
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure												
Repair		Requires repair, replacement or refurbishment						N/W		Not working												
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable												
    		Fluid escaping and dripping						N/C		Not checked												
    		Vehicle requires substantial work or restoration																				
    		Vehicle is in poor condition and in need of TLC																				
    		Vehicle is commensurate with age and useable																				
    		Vehicle is in very good condition																				
    		Vehicle is in excellent condition																				
Disclaimer																						
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																						
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																						
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																						
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																						
Page 2/2																						