

Observation Report		Classic Automobilia 0425 250 613 Maintenance, Modifications & Restorations					Auction Lot No	
Report No								
		ABN: 95 933 498 716					MVRL 38236	
Inspection Date	Make/Model				Year	Odometer - Mls / Km	VIN	
46069	Holden EK				1962	11,056mls	EK229 3093S	
		Overall Rating				Comments		
		1	1	1	1	1	Superb example and a joy to drive.	
EXTERIOR		Good	Fair	Repair	N/C	N/A	Comments	
Presentation	✓							
Glass	✓							
Bodywork	✓						Poor door fit. Bonnet moulding N/S.	
Paintwork	✓							
Lamps Condition	✓							
Bumper Bars	✓							
Brightwork	✓							
Seals	✓							
Convertible Roof					✓			
INTERIOR		Good	Fair	Repair	N/C	N/A	Comments	
Boot Area	✓						Some paint scratches in cargo area.	
Seats & Belts	✓							
Floor Coverings	✓							
Headlining/Visors	✓							
Trim	✓							
Doors	✓							
Windows and Mirrors	✓						R/H/R window N/W.	
Heating and Ventilation					✓			
Lights/Wipers/Washers/Horn	✓							
Other Electrical					✓			
Entertainment Equipment	✓							
ABS/SRS					✓			
UNDERBODY		Good	Fair	Repair	N/C	N/A	Comments	
Structure	✓							
Corrosion	✓							
Powertrain	✓						Fastener missing from R/H engine mount bracket (torn from chassis).	
Exhaust	✓							
Brakes	✓							
Wheels & Tyres	✓							
Steering & Suspension	✓							
Fuel System			✓				Carburettors leaking. Fuel hose perished.	
Fluid Leaks	✓						Engine and trans wet.	
							Pge 1/2	
ENGINE BAY		Good	Fair	Repair	N/C	N/A	Comments	
Presentation	✓							
Fluid Levels/Condition	✓							
Cooling System	✓							
Power Steering					✓			
Electrical	✓							
Engine Running			✓				Clanging noise especially on start up, suspect starter motor or ring gear.	
Air Conditioning					✓			
ROAD TEST		Good	Fair	Repair	N/C	N/A	Comments	
Engine Performance	✓							
Transmission	✓							
Noise and Vibration	✓							
Steering and Suspension	✓							
Braking	✓							
Clutch					✓			
Instruments	✓							
General Comments								

Key																					
Good		Operational or well presented at time of inspection						U/S		Unservicable											
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure											
Repair		Requires repair, replacement or refurbishment						N/W		Not working											
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable											
    		Fluid escaping and dripping						N/C		Not checked											
    		Vehicle requires substantial work or restoration																			
    		Vehicle is in poor condition and in need of TLC																			
    		Vehicle is commensurate with age and useable																			
    		Vehicle is in very good condition																			
    		Vehicle is in excellent condition																			
Disclaimer																					
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																					
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																					
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																					
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																					
Page 2/2																					