

Observation Report



Report No

Auction Lot No
3

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
4 June 2026	Stutz Model BB Coupe	1928		BB-C10-BB25L

EXTERIOR

	Good	Fair	Repair	N/C	N/A	Comments
Presentation	☒	☐	☐	☐	☐	Oily Rag survivor with lots of character, nicely recommissioned
Glass	☒	☐	☐	☐	☐	
Bodywork	☒	☐	☐	☐	☐	Surface rust in a few places, some repairs & minor dents
Paintwork	☐	☒	☐	☐	☐	Old paint that has been nicely preserved
Lamps Condition	☒	☐	☐	☐	☐	
Bumper Bars	☒	☐	☐	☐	☐	
Brightwork	☒	☐	☐	☐	☐	
Seals	☒	☐	☐	☐	☐	
Convertible Roof	☐	☐	☐	☐	☒	

INTERIOR

	Good	Fair	Repair	N/C	N/A	Comments
Boot Area	☒	☐	☐	☐	☐	Dickey seat/golf club compartment
Seats & Belts	☒	☐	☐	☐	☐	Older with nice patina
Floor Coverings	☒	☐	☐	☐	☐	Ditto
Headlining/Visors	☒	☐	☐	☐	☐	Ditto
Trim	☒	☐	☐	☐	☐	Ditto
Doors	☒	☐	☐	☐	☐	Ditto
Windows and Mirrors	☒	☐	☐	☐	☐	
Heating and Ventilation	☒	☐	☐	☐	☐	Windscreen & windows all open
Lights/Wipers/Washers/Horn	☒	☐	☐	☐	☐	
Other Electrical	☐	☐	☐	☒	☐	
Entertainment Equipment	☐	☐	☐	☒	☐	
ABS/SRS	☐	☐	☐	☐	☒	

UNDERBODY

	Good	Fair	Repair	N/C	N/A	Comments
Structure	☒	☐	☐	☐	☐	Solid body and chassis
Corrosion	☒	☐	☐	☐	☐	None evident
Powertrain	☒	☐	☐	☐	☐	Engine & transaxle good
Exhaust	☒	☐	☐	☐	☐	
Brakes	☒	☐	☐	☐	☐	Hydraulic brakes function well
Wheels & Tyres	☒	☐	☐	☐	☐	Spokes present & tight
Steering & Suspension	☒	☐	☐	☐	☐	No excessive play or wear
Fuel System	☒	☐	☐	☐	☐	
Fluid Leaks	☒	☐	☐	☐	☐	Minor (preset) seepage, water pump gland

Page 1/2

ENGINE BAY

	Good	Fair	Repair	N/C	N/A	Comments
Presentation	☒	☐	☐	☐	☐	Commensurate with exterior
Fluid Levels/Condition	☒	☐	☐	☐	☐	
Cooling System	☒	☐	☐	☐	☐	
Power Steering	☐	☐	☐	☐	☒	

Electrical	☒	☐	☐	☐	☐	
Engine Running	☒	☐	☐	☐	☐	
Air Conditioning	☐	☐	☐	☐	☒	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	☒	☐	☐	☐	☐	Lovely car to drive, performs well & mechanically sound
Transmission	☒	☐	☐	☐	☐	
Noise and Vibration	☒	☐	☐	☐	☐	
Steering and Suspension	☒	☐	☐	☐	☐	
Braking	☒	☐	☐	☐	☐	
Clutch	☒	☐	☐	☐	☐	
Instruments	☐	☐	☒	☐	☐	Speedo not working

Key			
Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked

Disclaimer
This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.