

Observation Report



Report No

ABN: 21 625 963 475

Auction Lot No

LMCT: MCT-00412355 (VIC) -
MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
14/8/2026	Ferrari 308 GTB	1977	37,739	F106AB20851

EXTERIOR

	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓	☐	☐	☐	☐	
Glass	✓	☐	☐	☐	☐	
Bodywork	✓	☐	☐	☐	☐	
Paintwork	✓	☐	☐	☐	☐	
Lamps Condition	✓	☐	☐	☐	☐	
Bumper Bars	✓	☐	☐	☐	☐	
Brightwork	☐	☐	☐	☐	☐	
Seals	✓	☐	☐	☐	☐	
Convertible Roof	☐	☐	☐	☐	☐	

INTERIOR

	Good	Fair	Repair	N/C	N/A	Comments
Boot Area	☐	☐	☐	☐	☐	
Seats & Belts	✓	☐	☐	☐	☐	
Floor Coverings	✓	☐	☐	☐	☐	
Headlining/Visors	✓	☐	☐	☐	☐	
Trim	✓	☐	☐	☐	☐	
Doors	☐	☐	✓	☐	☐	Drivers door speaker cover missing
Windows and Mirrors	✓	☐	☐	☐	☐	Exterior mirrors need tightening
Heating and Ventilation	☐	☐	☐	☐	☐	
Lights/Wipers/Washers/Horn	☐	☐	☐	☐	☐	
Other Electrical	☐	☐	☐	☐	☐	
Entertainment Equipment	☐	☐	☐	☐	☐	
ABS/SRS	☐	☐	☐	☐	☐	

UNDERBODY

	Good	Fair	Repair	N/C	N/A	Comments
Structure	✓	☐	☐	☐	☐	
Corrosion	✓	☐	☐	☐	☐	
Powertrain	☐	☐	✓	☐	☐	Drive shafts need repair
Exhaust	☐	✓	☐	☐	☐	
Brakes	☐	☐	☐	☐	☐	
Wheels & Tyres	✓	☐	☐	☐	☐	
Steering & Suspension	☐	☐	✓	☐	☐	Front suspension bushes replace

Fuel System	✓	☐	☐	☐	☐	Slight engine oil weep
Fluid Leaks	☐	☐	✓	☐	☐	Slight engine oil weep

ENGINE BAY

	Good	Fair	Repair	N/C	N/A	Comments
Presentation	☐	✓	☐	☐	☐	
Fluid Levels/Condition	☐	✓	☐	☐	☐	
Cooling System	☐	✓	☐	☐	☐	
Power Steering	☐	✓	☐	☐	☐	
Electrical	☐	✓	☐	☐	☐	
Engine Running	☐	✓	☐	☐	☐	
Air Conditioning	☐	✓	☐	☐	☐	

ROAD TEST

	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	☐	✓	☐	☐	☐	
Transmission	☐	✓	☐	☐	☐	
Noise and Vibration	☐	✓	☐	☐	☐	
Steering and Suspension	☐	☐	☐	☐	☐	
Braking	☐	☐	☐	☐	☐	
Clutch	☐	☐	☐	☐	☐	
Instruments	☐	☐	☐	☐	☐	

Key			
Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked
Disclaimer			
This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle. The following items are not included in this inspection report: - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal components. This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.			