

Observation Report



Report No: 09/2670

ABN: 21 625 963 475

Auction Lot No 70

LMCT: MCT-00412355 (VIC) -
MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
14/8/26	RILEY 2.5 RMB CABRIOLET	1950	46,266	60D7119

EXTERIOR

	Good	Fair	Repair	N/C	N/A	Comments
Presentation	☐	☒	☐	☐	☐	Drivers side outer door handle repair
Glass	☐	☒	☐	☐	☐	
Bodywork	☒	☐	☐	☐	☐	
Paintwork	☐	☒	☐	☐	☐	
Lamps Condition	☐	☒	☒	☐	☐	Some lamps need repair
Bumper Bars	☐	☒	☐	☐	☐	
Brightwork	☐	☒	☐	☐	☐	
Seals	☐	☒	☐	☐	☐	
Convertible Roof	☐	☒	☐	☐	☐	

INTERIOR

	Good	Fair	Repair	N/C	N/A	Comments
Boot Area	☐	☒	☐	☐	☐	
Seats & Belts	☐	☒	☒	☐	☐	Steering wheel requires repair
Floor Coverings	☐	☒	☐	☐	☐	
Headlining/Visors	☐	☒	☐	☐	☐	
Trim	☐	☒	☐	☐	☐	
Doors	☐	☒	☐	☐	☐	
Windows and Mirrors	☐	☒	☐	☐	☐	
Heating and Ventilation	☐	☒	☐	☐	☐	
Lights/Wipers/Washers/Horn	☐	☒	☐	☐	☐	
Other Electrical	☐	☐	☒	☐	☐	
Entertainment Equipment	☐	☒	☐	☐	☐	
ABS/SRS	☐	☐	☐	☐	☐	

UNDERBODY

	Good	Fair	Repair	N/C	N/A	Comments
Structure	☐	☒	☐	☐	☐	
Corrosion	☐	☒	☐	☐	☐	
Powertrain	☐	☐	☒	☐	☐	Oil leak/weep noted – diff, gearbox, engine
Exhaust	☐	☒	☐	☐	☐	
Brakes	☐	☐	☒	☐	☐	

Wheels & Tyres	☐	☐	✓	☐	☐	
Steering & Suspension	☐	☐	✓	☐	☐	
Fuel System	☐	✓	☐	☐	☐	
Fluid Leaks	☐	☐	✓	☐	☐	

ENGINE BAY

	Good	Fair	Repair	N/C	N/A	Comments
Presentation	☐	☐	✓	☐	☐	
Fluid Levels/Condition	☐	☐	✓	☐	☐	
Cooling System	☐	☐	✓	☐	☐	Needs repair
Power Steering	☐	☐	☐	✓	☐	
Electrical	☐	☐	☐	✓	☐	
Engine Running	☐	✓	☐	☐	☐	Vehicle started see video
Air Conditioning	☐	☐	☐	☐	✓	

ROAD TEST

	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	☐	☐	☐	✓	☐	no road test
Transmission	☐	☐	☐	✓	☐	
Noise and Vibration	☐	☐	☐	✓	☐	
Steering and Suspension	☐	☐	☐	✓	☐	
Braking	☐	☐	☐	✓	☐	
Clutch	☐	☐	☐	✓	☐	
Instruments	☐	☐	☐	✓	☐	

Key

Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked

Disclaimer

This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report: - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal components.

This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.