

Observation Report



Report No

Auction Lot No
1

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
26 August 2026	Ford Cortina Mark II GT	1970	63434 mi	CN2970C

EXTERIOR

	Good	Fair	Repair	N/C	N/A	Comments
Presentation	☒	☐	☐	☐	☐	Very tidy, original example
Glass	☒	☐	☐	☐	☐	
Bodywork	☒	☐	☐	☐	☐	
Paintwork	☒	☐	☐	☐	☐	
Lamps Condition	☒	☐	☐	☐	☐	
Bumper Bars	☒	☐	☐	☐	☐	
Brightwork	☒	☐	☐	☐	☐	Small dents in brightwork along leading edge of bonnet
Seals	☒	☐	☐	☐	☐	
Convertible Roof	☐	☐	☐	☐	☒	

INTERIOR

	Good	Fair	Repair	N/C	N/A	Comments
Boot Area	☒	☐	☐	☐	☐	
Seats & Belts	☒	☐	☐	☐	☐	Front seats recently recovered
Floor Coverings	☒	☐	☐	☐	☐	
Headlining/Visors	☒	☐	☐	☐	☐	
Trim	☒	☐	☐	☐	☐	Steering wheel & instruments showing some age
Doors	☒	☐	☐	☐	☐	
Windows and Mirrors	☒	☐	☐	☐	☐	
Heating and Ventilation	☒	☐	☐	☐	☐	
Lights/Wipers/Washers/Horn	☐	☐	☒	☐	☐	Parking lights front/rear not working
Other Electrical	☒	☐	☐	☐	☐	
Entertainment Equipment	☐	☐	☐	☒	☐	
ABS/SRS	☐	☐	☐	☐	☒	

UNDERBODY

	Good	Fair	Repair	N/C	N/A	Comments
Structure	☒	☐	☐	☐	☐	
Corrosion	☒	☐	☐	☐	☐	
Powertrain	☒	☐	☐	☐	☐	
Exhaust	☒	☐	☐	☐	☐	
Brakes	☒	☐	☐	☐	☐	
Wheels & Tyres	☐	☒	☐	☐	☐	Front tyres good, older rear tyres need replacing
Steering & Suspension	☒	☐	☐	☐	☐	
Fuel System	☒	☐	☐	☐	☐	
Fluid Leaks	☒	☐	☐	☐	☐	As expected

Page 1/2

ENGINE BAY

	Good	Fair	Repair	N/C	N/A	Comments
Presentation	☒	☐	☐	☐	☐	
Fluid Levels/Condition	☒	☐	☐	☐	☐	
Cooling System	☒	☐	☐	☐	☐	
Power Steering	☒	☐	☐	☐	☐	

Electrical	☒	☐	☐	☐	☐	Needs tuning
Engine Running	☐	☒	☐	☐	☐	
Air Conditioning	☐	☐	☐	☐	☒	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	☐	☒	☐	☐	☐	Drives well but engine would benefit from a tune
Transmission	☒	☐	☐	☐	☐	
Noise and Vibration	☒	☐	☐	☐	☐	
Steering and Suspension	☒	☐	☐	☐	☐	
Braking	☒	☐	☐	☐	☐	
Clutch	☒	☐	☐	☐	☐	
Instruments	☒	☐	☐	☐	☐	

Key			
Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked

Disclaimer
This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.