

Observation Report



Auction Lot No

11

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
26 August 2026	Ford Mustang Grande 351	1973	75038 mi	3F04H142194

EXTERIOR

Good Fair Repair N/C N/A Comments

Presentation	✓						
Glass		✓					Small scratches in a few places
Bodywork	✓						
Paintwork		✓					Bonnet slightly mismatched, small scratch on rear wing & fender
Lamps Condition	✓						
Bumper Bars		✓					Marks on rear bar
Brightwork	✓						
Seals	✓						
Convertible Roof						✓	

INTERIOR

Good Fair Repair N/C N/A Comments

Boot Area	✓						
Seats & Belts	✓						
Floor Coverings	✓						
Headlining/Visors	✓						
Trim		✓					Dash pad has one very small crack evident
Doors		✓					LHS door card arm rest has some damage
Windows and Mirrors	✓						
Heating and Ventilation	✓						
Lights/Wipers/Washers/Horn	✓						
Other Electrical	✓						
Entertainment Equipment				✓			Aftermarket CD player
ABS/SRS						✓	

UNDERBODY

Good Fair Repair N/C N/A Comments

Structure	✓						
Corrosion		✓					Minor activity evident under paint in both 3/4 panels
Powertrain	✓						
Exhaust	✓						
Brakes	✓						
Wheels & Tyres			✓				Older (2015) tyres cracked and need replacing
Steering & Suspension	✓						Modified to modern rack
Fuel System	✓						
Fluid Leaks	✓						Minor seepage in keeping with a vehicle of this type

Page 1/2

ENGINE BAY

Good Fair Repair N/C N/A Comments

Presentation	✓						
Fluid Levels/Condition	✓						
Cooling System	✓						
Power Steering	✓						

Electrical	☒	☐	☐	☐	☐	Compressor has been removed
Engine Running	☒	☐	☐	☐	☐	
Air Conditioning	☐	☐	☐	☐	☒	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	☐	☒	☐	☐	☐	Needs a tune
Transmission	☒	☐	☐	☐	☐	Aftermarket steering wheel, some wear to rim
Noise and Vibration	☒	☐	☐	☐	☐	
Steering and Suspension	☒	☐	☐	☐	☐	
Braking	☒	☐	☐	☐	☐	
Clutch	☐	☐	☐	☐	☒	
Instruments	☒	☐	☐	☐	☐	

Key			
Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked

Disclaimer
This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.