

Observation Report



Auction Lot No

12

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
26 August 2026	Ford F-150 SVT Lightning	2003	92419 km	2FTRF07313CA692

EXTERIOR

Good Fair Repair N/C N/A Comments

Presentation	☒	☐	☐	☐	☐	
Glass	☒	☐	☐	☐	☐	
Bodywork	☒	☐	☐	☐	☐	Marks on LHS step
Paintwork	☒	☐	☐	☐	☐	Minor stone chips evident all over, particularly on bed lid
Lamps Condition	☒	☐	☐	☐	☐	
Bumper Bars	☒	☐	☐	☐	☐	Minor scuffs on lower section of front bar
Brightwork	☒	☐	☐	☐	☐	
Seals	☒	☐	☐	☐	☐	
Convertible Roof	☐	☐	☐	☐	☒	

INTERIOR

Good Fair Repair N/C N/A Comments

Boot Area	☒	☐	☐	☐	☐	
Seats & Belts	☒	☐	☐	☐	☐	Would benefit from a clean
Floor Coverings	☒	☐	☐	☐	☐	
Headlining/Visors	☒	☐	☐	☐	☐	
Trim	☒	☐	☐	☐	☐	
Doors	☒	☐	☐	☐	☐	
Windows and Mirrors	☒	☐	☐	☐	☐	
Heating and Ventilation	☒	☐	☐	☐	☐	
Lights/Wipers/Washers/Horn	☒	☐	☐	☐	☐	
Other Electrical	☒	☐	☐	☐	☐	
Entertainment Equipment	☒	☐	☐	☐	☐	
ABS/SRS	☐	☐	☐	☒	☐	

UNDERBODY

Good Fair Repair N/C N/A Comments

Structure	☒	☐	☐	☐	☐	
Corrosion	☒	☐	☐	☐	☐	None observed
Powertrain	☒	☐	☐	☐	☐	
Exhaust	☒	☐	☐	☐	☐	
Brakes	☒	☐	☐	☐	☐	Ceramic pads need heat to work effectively
Wheels & Tyres	☐	☒	☐	☐	☐	Some kerbing evident on rims, tyres have good tread
Steering & Suspension	☐	☐	☒	☐	☐	Rear bushings and bump stops need repair, pitman & idler
Fuel System	☒	☐	☐	☐	☐	
Fluid Leaks	☒	☐	☐	☐	☐	

Pge 1/2

ENGINE BAY

Good Fair Repair N/C N/A Comments

Presentation	☐	☒	☐	☐	☐	Some belts showing age
Fluid Levels/Condition	☒	☐	☐	☐	☐	
Cooling System	☒	☐	☐	☐	☐	
Power Steering	☒	☐	☐	☐	☐	

Electrical	☒	☐	☐	☐	☐	Not blowing cold, needs regassing
Engine Running	☒	☐	☐	☐	☐	
Air Conditioning	☐	☐	☒	☐	☐	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	☐	☒	☐	☐	☐	Running lean
Transmission	☒	☐	☐	☐	☐	Engine mounts need replacing
Noise and Vibration	☐	☐	☒	☐	☐	
Steering and Suspension	☐	☒	☐	☐	☐	
Braking	☒	☐	☐	☐	☐	Would benefit from repairs outlined above
Clutch	☐	☐	☐	☐	☒	
Instruments	☒	☐	☐	☐	☐	

Key			
Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked

Disclaimer
This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.