

Observation Report



Auction Lot No

16

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
26 August 2026	Rolls-Royce Silver Shadow	1973	42839 mi	SRH14461

EXTERIOR

Good Fair Repair N/C N/A Comments

Presentation	☒	☐	☐	☐	☐	
Glass	☐	☒	☐	☐	☐	
Bodywork	☐	☒	☐	☐	☐	
Paintwork	☐	☒	☐	☐	☐	Older (possibly original), worn through and thin in places
Lamps Condition	☒	☐	☐	☐	☐	
Bumper Bars	☐	☒	☐	☐	☐	
Brightwork	☐	☒	☐	☐	☐	Chrome showing age
Seals	☐	☒	☐	☐	☐	
Convertible Roof	☐	☐	☐	☐	☒	

INTERIOR

Good Fair Repair N/C N/A Comments

Boot Area	☒	☐	☐	☐	☐	
Seats & Belts	☒	☐	☐	☐	☐	Some wear on seats but would rejuvenate well
Floor Coverings	☒	☐	☐	☐	☐	Good for original mats & age
Headlining/Visors	☒	☐	☐	☐	☐	
Trim	☐	☒	☐	☐	☐	Timber laquer aged, some cracks on dash & centre panels
Doors	☒	☐	☐	☐	☐	
Windows and Mirrors	☒	☐	☐	☐	☐	
Heating and Ventilation	☒	☐	☐	☐	☐	
Lights/Wipers/Washers/Horn	☒	☐	☐	☐	☐	
Other Electrical	☐	☐	☒	☐	☐	Driver's side seat adjustment n/w
Entertainment Equipment	☐	☐	☐	☒	☐	Period tape deck
ABS/SRS	☐	☐	☐	☐	☒	

UNDERBODY

Good Fair Repair N/C N/A Comments

Structure	☒	☐	☐	☐	☐	
Corrosion	☒	☐	☐	☐	☐	None observed
Powertrain	☒	☐	☐	☐	☐	
Exhaust	☒	☐	☐	☐	☐	
Brakes	☒	☐	☐	☐	☐	
Wheels & Tyres	☒	☐	☐	☐	☐	Tyres date code 36-2018
Steering & Suspension	☒	☐	☐	☐	☐	
Fuel System	☒	☐	☐	☐	☐	
Fluid Leaks	☒	☐	☐	☐	☐	Some seepage typical of cars of this type and age

Page 1/2

ENGINE BAY

Good Fair Repair N/C N/A Comments

Presentation	☒	☐	☐	☐	☐	
Fluid Levels/Condition	☒	☐	☐	☐	☐	
Cooling System	☒	☐	☐	☐	☐	
Power Steering	☒	☐	☐	☐	☐	

Electrical	☒	☐	☐	☐	☐	
Engine Running	☒	☐	☐	☐	☐	
Air Conditioning	☒	☐	☐	☐	☐	Blows cold

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	☒	☐	☐	☐	☐	Performs well, running gear in good order
Transmission	☒	☐	☐	☐	☐	
Noise and Vibration	☒	☐	☐	☐	☐	
Steering and Suspension	☒	☐	☐	☐	☐	Drag link RH ball joint worn
Braking	☒	☐	☐	☐	☐	
Clutch	☒	☐	☐	☐	☐	
Instruments	☒	☐	☐	☐	☐	

Key			
Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked

Disclaimer
This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.