

Observation Report



Auction Lot No

18

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
27 August 2026	Peugeot 404 Station Wagon	1969	33598 mi	1936258

EXTERIOR

Good Fair Repair N/C N/A Comments

Presentation		✓				Scruffy survivor
Glass		✓				
Bodywork		✓				Lots of dents & dings, rust evident in various places
Paintwork		✓				Very old flat paint, lots of stone chips & stress cracks
Lamps Condition	✓					
Bumper Bars		✓				Scratched
Brightwork		✓				
Seals			✓			Aged & perished door rubbers & window seals
Convertible Roof					✓	

INTERIOR

Good Fair Repair N/C N/A Comments

Boot Area		✓				Rear tailgate panel n/s
Seats & Belts		✓				Later front seats with headrests, small split in LH upper se
Floor Coverings					✓	Front mats only, no sound deadening
Headlining/Visors		✓				
Trim		✓				Old and tatty, steering wheel cracked, dash pad cracked
Doors		✓				As above
Windows and Mirrors		✓				
Heating and Ventilation				✓		
Lights/Wipers/Washers/Horn						RH Indicators n/w - likely an earth problem
Other Electrical				✓		Starter button added
Entertainment Equipment			✓			Old radio n/w, LHS rear speaker on floor
ABS/SRS					✓	

UNDERBODY

Good Fair Repair N/C N/A Comments

Structure	✓					
Corrosion		✓				Floors patched, evidence of previous rust repairs
Powertrain	✓					
Exhaust			✓			Has exhaust leak
Brakes	✓					
Wheels & Tyres		✓				24-2007
Steering & Suspension		✓				
Fuel System	✓					
Fluid Leaks		✓				Typical of a vehicle of this age and type

Page 1/2

ENGINE BAY

Good Fair Repair N/C N/A Comments

Presentation		✓				
Fluid Levels/Condition		✓				
Cooling System		✓				
Power Steering					✓	

Electrical	☐	☒	☐	☐	☐	Engine rattles against body - mounts need replacing
Engine Running	☐	☐	☒	☐	☐	
Air Conditioning	☐	☐	☐	☐	☒	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	☐	☒	☐	☐	☐	Not running well due to old fuel
Transmission	☒	☐	☐	☐	☐	Noisy due to lack of insulation
Noise and Vibration	☐	☒	☐	☐	☐	
Steering and Suspension	☒	☐	☐	☐	☐	
Braking	☒	☐	☐	☐	☐	
Clutch	☒	☐	☐	☐	☐	
Instruments	☒	☐	☐	☐	☐	

Key			
Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked

Disclaimer
This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.