

Observation Report



Auction Lot No

2

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
27 August 2026	Chevrolet Deluxe Convertible	1952	63488 mi	9KK-E 26492

EXTERIOR

Good Fair Repair N/C N/A Comments

Presentation	☐	☒	☐	☐	☐	
Glass	☒	☐	☐	☐	☐	
Bodywork	☐	☒	☐	☐	☐	Activity evident under paint in several places inc. lower door
Paintwork	☐	☒	☐	☐	☐	Older repaint has some stone chips & marks
Lamps Condition	☒	☐	☐	☐	☐	
Bumper Bars	☐	☒	☐	☐	☐	Pitting evident, small area of damage above front no. plate
Brightwork	☐	☒	☐	☐	☐	Pitting in places
Seals	☐	☒	☐	☐	☐	
Convertible Roof	☒	☐	☐	☐	☐	Works but hydraulic oil needs topping up

INTERIOR

Good Fair Repair N/C N/A Comments

Boot Area	☐	☒	☐	☐	☐	
Seats & Belts	☒	☐	☐	☐	☐	
Floor Coverings	☐	☒	☐	☐	☐	
Headlining/Visors	☒	☐	☐	☐	☐	
Trim	☐	☒	☐	☐	☐	Some small marks, would benefit from cleaning
Doors	☒	☐	☐	☐	☐	
Windows and Mirrors	☒	☐	☐	☐	☐	
Heating and Ventilation	☒	☐	☐	☐	☐	
Lights/Wipers/Washers/Horn	☒	☐	☐	☐	☐	
Other Electrical	☒	☐	☐	☐	☐	Wind-up clock works
Entertainment Equipment	☐	☐	☐	☐	☒	
ABS/SRS	☐	☐	☐	☐	☒	

UNDERBODY

Good Fair Repair N/C N/A Comments

Structure	☒	☐	☐	☐	☐	Chassis has opening cut into LH rear X frame for cable
Corrosion	☒	☐	☐	☐	☐	None observed
Powertrain	☐	☒	☐	☐	☐	
Exhaust	☒	☐	☐	☐	☐	
Brakes	☒	☐	☐	☐	☐	
Wheels & Tyres	☐	☒	☐	☐	☐	04-2016
Steering & Suspension	☒	☐	☐	☐	☐	Modified to rack and pinion power steering
Fuel System	☒	☐	☐	☐	☐	
Fluid Leaks	☒	☐	☐	☐	☐	

Page 1/2

ENGINE BAY

Good Fair Repair N/C N/A Comments

Presentation	☐	☒	☐	☐	☐	
Fluid Levels/Condition	☒	☐	☐	☐	☐	
Cooling System	☒	☐	☐	☐	☐	
Power Steering	☒	☐	☐	☐	☐	

Electrical	☒	☐	☐	☐	☐	Engine has knock until oil pressure comes up
Engine Running	☐	☐	☒	☐	☐	
Air Conditioning	☐	☐	☐	☐	☒	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	☐	☐	☒	☐	☐	Detonating due to plugs that are too hot
Transmission	☒	☐	☐	☐	☐	
Noise and Vibration	☒	☐	☐	☐	☐	
Steering and Suspension	☒	☐	☐	☐	☐	
Braking	☒	☐	☐	☐	☐	
Clutch	☒	☐	☐	☐	☐	
Instruments	☒	☐	☐	☐	☐	

Key			
Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked

Disclaimer
This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.