

Observation Report



Auction Lot No

3

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
27 August 2026	Mercedes-Benz 300CE-24	1990	252238 kr	WDB1240512B2040

EXTERIOR

Good Fair Repair N/C N/A Comments

Presentation	✓						
Glass		✓					Lightly scratched on side windows
Bodywork	✓						Driver's door fit needs adjustment
Paintwork	✓						Stone chips and few scratches, RH rear quarter repainted
Lamps Condition	✓						
Bumper Bars	✓						Minor scuff marks on front & rear bars
Brightwork	✓						Grille has damage on lower section, star mascot pitted
Seals	✓						
Convertible Roof						✓	Sunroof not tilting

INTERIOR

Good Fair Repair N/C N/A Comments

Boot Area	✓						
Seats & Belts		✓					Driver's side bolster has some wear, headrest adjust n/w
Floor Coverings	✓						
Headlining/Visors	✓						LHS A-pillar cover peeling
Trim		✓					Timber facia has some delamination
Doors	✓						
Windows and Mirrors	✓						
Heating and Ventilation	✓						
Lights/Wipers/Washers/Horn	✓						
Other Electrical	✓						
Entertainment Equipment	✓						
ABS/SRS						✓	

UNDERBODY

Good Fair Repair N/C N/A Comments

Structure	✓						
Corrosion	✓						
Powertrain	✓						
Exhaust		✓					Hole in silencer
Brakes	✓						
Wheels & Tyres		✓					03-2016 showing age
Steering & Suspension			✓				Lower arm bushings & lower ball joint boots need replacing
Fuel System	✓						
Fluid Leaks	✓						

Page 1/2

ENGINE BAY

Good Fair Repair N/C N/A Comments

Presentation	✓						
Fluid Levels/Condition	✓						
Cooling System	✓						
Power Steering		✓					Steering damper needs replacing

Electrical	☒	☐	☐	☐	☐	Engine mounts & prop shaft couplings need replacing
Engine Running	☐	☒	☐	☐	☐	
Air Conditioning	☒	☐	☐	☐	☐	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	☒	☐	☐	☐	☐	Would benefit from oil change & service
Transmission	☐	☒	☐	☐	☐	
Noise and Vibration	☒	☐	☐	☐	☐	Front suspension needs some work as noted above
Steering and Suspension	☐	☒	☐	☐	☐	
Braking	☒	☐	☐	☐	☐	
Clutch	☒	☐	☐	☐	☐	
Instruments	☒	☐	☐	☐	☐	

Key			
Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked

Disclaimer
This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.