

Observation Report



Auction Lot No

8

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
27 August 2026	Essex Super Six Boattail Speedster	1927	83977 mi	610822

EXTERIOR

Good Fair Repair N/C N/A Comments

Presentation		✓				Older restoration, not running after extended period off road
Glass		✓				Windscreen lightly scratched
Bodywork		✓				LHF guard has dent above wheelarch
Paintwork		✓				Several paint touch ups, activity under paint in places
Lamps Condition	✓					
Bumper Bars	✓					
Brightwork		✓				
Seals		✓				
Convertible Roof		✓				

INTERIOR

Good Fair Repair N/C N/A Comments

Boot Area					✓	
Seats & Belts		✓				
Floor Coverings		✓				
Headlining/Visors					✓	
Trim			✓			Steering wheel timber broken & needs repairing
Doors		✓				
Windows and Mirrors		✓				
Heating and Ventilation				✓		
Lights/Wipers/Washers/Horn				✓		Some switches require lubrication
Other Electrical					✓	
Entertainment Equipment					✓	
ABS/SRS					✓	

UNDERBODY

Good Fair Repair N/C N/A Comments

Structure	✓					
Corrosion	✓					
Powertrain		✓				
Exhaust		✓				
Brakes		✓				
Wheels & Tyres	✓					Wheel spokes & older tyres still serviceable
Steering & Suspension		✓				
Fuel System		✓				
Fluid Leaks		✓				Seepage in keeping with vehicle's age and type

Page 1/2

ENGINE BAY

Good Fair Repair N/C N/A Comments

Presentation		✓				
Fluid Levels/Condition	✓					
Cooling System				✓		
Power Steering					✓	

Electrical			✓			Battery dead
Engine Running		✓				Engine runs but not building oil pressure
Air Conditioning					✓	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance					✓	Not tested
Transmission					✓	
Noise and Vibration					✓	
Steering and Suspension					✓	
Braking					✓	
Clutch					✓	
Instruments					✓	

Key			
Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked

Disclaimer
This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.