

Observation Report



Auction Lot No

9

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
27 August 2026	MG TD Special	1950	85649 mi	TD 01480

EXTERIOR

Good Fair Repair N/C N/A Comments

Presentation	✓						
Glass	✓						
Bodywork		✓					
Paintwork		✓					Flat in places, some stone chips etc.
Lamps Condition		✓					Headlight buckets old
Bumper Bars						✓	
Brightwork		✓					
Seals						✓	
Convertible Roof						✓	None

INTERIOR

Good Fair Repair N/C N/A Comments

Boot Area						✓	
Seats & Belts	✓						
Floor Coverings		✓					
Headlining/Visors						✓	
Trim		✓					Panel behind seats n/s
Doors						✓	
Windows and Mirrors		✓					
Heating and Ventilation				✓			
Lights/Wipers/Washers/Horn				✓			
Other Electrical			✓				Oil pressure gauge n/w, ignition switch faulty
Entertainment Equipment						✓	
ABS/SRS						✓	

UNDERBODY

Good Fair Repair N/C N/A Comments

Structure	✓						
Corrosion	✓						
Powertrain	✓						
Exhaust	✓						
Brakes	✓						
Wheels & Tyres		✓					33-2011
Steering & Suspension			✓				Bushes need replacing
Fuel System			✓				Fuel pump leaks
Fluid Leaks	✓						Typical for a vehicle of this age

Page 1/2

ENGINE BAY

Good Fair Repair N/C N/A Comments

Presentation		✓					
Fluid Levels/Condition		✓					
Cooling System		✓					Radiator bottom hose was leaking, fixed
Power Steering						✓	

Electrical	☒	☐	☒	☐	☐	Battery needs replacing
Engine Running	☒	☐	☐	☐	☐	Hard to start when cold
Air Conditioning	☐	☐	☐	☐	☒	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	☒	☐	☐	☐	☐	Drove well after extended period off the road
Transmission	☒	☐	☐	☐	☐	
Noise and Vibration	☒	☐	☐	☐	☐	
Steering and Suspension	☒	☐	☐	☐	☐	
Braking	☒	☐	☐	☐	☐	
Clutch	☒	☐	☐	☐	☐	
Instruments	☒	☐	☐	☐	☐	

Key			
Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked

Disclaimer
This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.