

Observation Report



Auction Lot No

13

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - MIs / Km	VIN
27 August 2026	Buick Eight Special Sports Coupe	1940	1269 mi	13650399

EXTERIOR

Good Fair Repair N/C N/A Comments

Presentation	✓					Nice straight body
Glass	✓					Rear window lightly scratched
Bodywork	✓					Small rust bubble on bonnet
Paintwork	✓					Few minor stone chips evident
Lamps Condition	✓					Lenses not cracked or faded
Bumper Bars	✓					Some very light pitting but not damaged
Brightwork		✓				Some pitting, wheel trims have few dents
Seals	✓					
Convertible Roof					✓	

INTERIOR

Good Fair Repair N/C N/A Comments

Boot Area			✓			Boot latch not fitted, otherwise tidy
Seats & Belts	✓					
Floor Coverings	✓					
Headlining/Visors	✓					
Trim	✓					
Doors	✓					
Windows and Mirrors	✓					
Heating and Ventilation				✓		
Lights/Wipers/Washers/Horn				✓		
Other Electrical				✓		
Entertainment Equipment				✓		
ABS/SRS					✓	

UNDERBODY

Good Fair Repair N/C N/A Comments

Structure	✓					
Corrosion	✓					None observed
Powertrain	✓					Car run briefly on carburettor after extended storage
Exhaust				✓		
Brakes			✓			Seized
Wheels & Tyres			✓			Old crossply tyres, still good tread
Steering & Suspension				✓		
Fuel System				✓		
Fluid Leaks				✓		Light seepage

Page 1/2

ENGINE BAY

Good Fair Repair N/C N/A Comments

Presentation	✓					
Fluid Levels/Condition		✓				
Cooling System		✓				Not leaking
Power Steering					✓	

Electrical			✓			No battery fitted
Engine Running	✓					Good oil pressure
Air Conditioning					✓	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance				✓		Car not tested due to seized brakes
Transmission				✓		
Noise and Vibration				✓		
Steering and Suspension				✓		
Braking				✓		
Clutch				✓		
Instruments				✓		

Key			
Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
Leaking	Fluid escaping and dripping	N/C	Not checked

Disclaimer
This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.