Observation Report

Report No

Donington AUCTIONS & SALES

Auction Lot No
4

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
23 November, 2026	Rolls-Royce Silver Dawn	1951	70989mi	SDB70

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✔				
Glass		✔				Some scratches
Bodywork	✔					
Paintwork		✔				Older, fair quality repaint with lots of stone chips etc.
Lamps Condition		✔				
Bumper Bars	✔					
Brightwork	✔					
Seals		✔				Some seals show age
Convertible Roof					✔	

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area		✔				
Seats & Belts			✔			Cracking, needs repairs
Floor Coverings	✔					
Headlining/Visors	✔					
Trim		✔				Timberwork has been restored
Doors		✔				
Windows and Mirrors		✔				
Heating and Ventilation					✔	
Lights/Wipers/Washers/Horn		✔				
Other Electrical					✔	
Entertainment Equipment					✔	
ABS/SRS					✔	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure	✔					
Corrosion		✔				
Powertrain		✔				
Exhaust		✔				
Brakes			✔			
Wheels & Tyres		✔				Tyres dated 41-2020
Steering & Suspension						
Fuel System		✔				
Fluid Leaks		✔				

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✔				
Fluid Levels/Condition	✔					Requires a service
Cooling System	✔					Runs at 85 degrees
Power Steering					✔	

Electrical		✔				
Engine Running		✔				
Air Conditioning					✔	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance		✔				
Transmission	✔					
Noise and Vibration		✔				
Steering and Suspension	✔					
Braking			✔			Front brake circuit needs fluid & bleeding
Clutch		✔				Requires adjustment
Instruments	✔					Function

Key

Good	Operational or well presented at time of inspection	**U/S**	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	**N/S**	Not secure
Repair	Requires repair, replacement or refurbishment	**N/W**	Not working
Wetting	Fluid escaping with the potential to drip	**N/A**	Not Applicable
Leaking	Fluid escaping and dripping	**N/C**	Not checked

Disclaimer

This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal

This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.