			I		1		
Pre-Purchase Inspection			⊂lc	3 5:	Sic	= Automobilia	
Report No					04	-25 250 613 Auction Lot No	
			Main	tenar	nce, I	Modifications & Restorations 19	
		A D NI	0E 023	700	716	MAVDI 29226	
		ADIN:	95 933	438 ·	110	MVRL 38236	
Inspection Date				ı	Make/N	Model Year Odometer - VIN MIs / Km	Rating /5 5.0
45406					BMW :		All values will be rounded down to the nearest 0.5
		Ove	erall Ra	ting		Comments	
	1	1	1	1	1	Like new.	
EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments	Type 'a' for ticks
Presentation	<u> </u>		•				Type a for tiers
Glass	•						
Bodywork	V						
Paintwork	_						
Lamps Condition	✓						
Bumper Bars	✓						
Brightwork	✓						
Seals	~						
Convertible Roof					~		
INTERIOR	Good	Fair	Repair	N/C	N/A	Comments	
Boot Area	~						
Seats & Belts	~						
Floor Coverings	✓						
Headlining/Visors	~						
Trim	~						
Doors	~						
Windows and Mirrors	V						
Heating and Ventilation	V						
Lights/Wipers/Washers/Horn	V						
Other Electrical	V						
Entertainment Equipment ABS/SRS	~				_		
UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments	
Structure	✓		1			Both front sill lips deformed.	
Corrosion	V						
Powertrain	✓						
Exhaust			~			Centre muffler holed.	
Brakes	✓						
Wheels & Tyres	~						
Steering & Suspension	V						
Fuel System							
Fluid Leaks	~						
						Pge 1/2	
			_				
ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments	
Presentation Fluid Levels (Condition							
Fluid Levels/Condition							
Cooling System Power Steering	V						
Power Steering Electrical	V						
Engine Running							
Air Conditioning							
ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments	
Engine Performance	~						
Transmission	-						
Noise and Vibration	✓						
Steering and Suspension	~						
	~						
Braking							
Braking Clutch	~						
	✓						
Clutch	·					General Comments	

						Key									
Good Fair Repair Wetting	Commensu Requires re Fluid escap	al or well pre urate for age epair, replac ping with the ping and drip	e of vehic ement or e potenti	cle but h	as wear a		r			U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked				
★ ☆ ☆ ☆ ★ ★ ☆ ☆ ★ ★ ★ ☆	Vehicle requires substantial work or restoration Vehicle is in poor condition and in need of TLC Vehicle is commensurate with age and useable Vehicle is in very good condition Vehicle is in excellent condition														
nis is a visual inspection only o					8236). No		onents a					been			
Classic Automobilia (MVRL382	236) will not b	oe held liable	e or resp	onsible i	n regard: purchase Engine	s to any	claim(s) hicle.) in rela	tion	to this report or any impl					
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection. Pge 2/2												n.			