

Pre-Purchase Inspection		Classic Automobilia	
Report No	0425 250 613	Auction Lot No	
	Maintenance, Modifications & Restorations	12	

ABN: 95 933 498 716

MVRL 38236

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
45406	Jaguar MK2	1962	4,717mls	209510DN

Rating /5 **3.5**

All values will be rounded down to the nearest 0.5

Overall Rating					Comments
1	1	1	0.5	0	Vehicle is good overall and very usable.

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓					
Glass		✓				Windscreen poor.
Bodywork	✓					
Paintwork	✓					
Lamps Condition	✓					
Bumper Bars	✓					
Brightwork	✓					Tarnished.
Seals	✓					
Convertible Roof					✓	

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area	✓					
Seats & Belts	✓					
Floor Coverings	✓					
Headlining/Visors	✓					
Trim		✓				Woodgrain aged.
Doors	✓					
Windows and Mirrors	✓					
Heating and Ventilation			✓			Vent controls N/W. Fan N/W.
Lights/Wipers/Washers/Horn	✓					
Other Electrical	✓					
Entertainment Equipment			✓			N/W.
ABS/SRS					✓	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure	✓					
Corrosion	✓					Evidence of repair to R/H/F jacking point.
Powertrain	✓					
Exhaust		✓				
Brakes		✓				
Wheels & Tyres	✓					
Steering & Suspension		✓				
Fuel System	✓					
Fluid Leaks			✓			Final drive, steering box, transmission and oil filter housing leaking.

Page 1/2

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✓					
Fluid Levels/Condition	✓					
Cooling System			✓			Coolant dripping off R/H/R of engine.
Power Steering					✓	
Electrical		✓				
Engine Running	✓					
Air Conditioning					✓	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	✓					Slow to get to temperature. Accelerator sticks.
Transmission		✓				Crunches into second.
Noise and Vibration		✓				Few clunks and creaks.
Steering and Suspension	✓					
Braking		✓				Poor performance.
Clutch					✓	
Instruments		✓				Aged.

General Comments

Type 'a' for ticks

