

Pre-Purchase Inspection		<div style="border: 2px solid black; padding: 5px; text-align: center;"> Classic Automobilia 0425 250 613 Maintenance, Modifications & Restorations </div>				Auction Lot No	
Report No						14	
		ABN: 95 933 498 716		MVRL 38236			
Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN			
45406	Rolls Royce Silver Wraith II	1980	74,949km	LRH40568			
Overall Rating		Comments					
1	1	1	0.5	0	Overall a very good vehicle that needs some minor repairs.		
EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments	
Presentation	✓						
Glass	✓						
Bodywork	✓						
Paintwork	✓					Few chips and marks.	
Lamps Condition	✓						
Bumper Bars	✓						
Brightwork	✓						
Seals	✓						
Convertible Roof					✓		
INTERIOR	Good	Fair	Repair	N/C	N/A	Comments	
Boot Area	✓						
Seats & Belts			✓			Aged. Electric mechanisms N/W.	
Floor Coverings	✓						
Headlining/Visors	✓						
Trim	✓					Dash wood paneling N/S.	
Doors	✓						
Windows and Mirrors	✓						
Heating and Ventilation			✓			N/W.	
Lights/Wipers/Washers/Horn	✓						
Other Electrical	✓						
Entertainment Equipment	✓						
ABS/SRS					✓		
UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments	
Structure	✓						
Corrosion	✓						
Powertrain	✓						
Exhaust			✓			Leaking.	
Brakes	✓						
Wheels & Tyres		✓					
Steering & Suspension	✓						
Fuel System	✓						
Fluid Leaks		✓				Transmission dripping. Engine wet.	
Page 1/2							
ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments	
Presentation			✓			Evidence of rodent damage.	
Fluid Levels/Condition	✓						
Cooling System	✓						
Power Steering	✓					Belts slipping.	
Electrical			✓			Some minor rodent damage.	
Engine Running		✓				Not 100% smooth.	
Air Conditioning			✓			N/W.	
ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments	
Engine Performance	✓						
Transmission	✓						
Noise and Vibration	✓					Ticking noise behind dash.	
Steering and Suspension	✓						
Braking			✓			Excessive brake pedal travel.	
Clutch					✓		
Instruments	✓						
General Comments							

Rating /5 **3.5**
 All values will be rounded down to the nearest 0.5

Type 'a' for ticks

--

Key

Good	Operational or well presented at time of inspection	U/S	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	N/S	Not secure
Repair	Requires repair, replacement or refurbishment	N/W	Not working
Wetting	Fluid escaping with the potential to drip	N/A	Not Applicable
★ ☆ ☆ ☆ ☆	Fluid escaping and dripping	N/C	Not checked
★ ★ ☆ ☆ ☆	Vehicle requires substantial work or restoration		
★ ★ ★ ☆ ☆	Vehicle is in poor condition and in need of TLC		
★ ★ ★ ★ ☆	Vehicle is commensurate with age and useable		
★ ★ ★ ★ ★	Vehicle is in very good condition		
	Vehicle is in excellent condition		

Disclaimer

This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.

Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.

This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.