

Pre-Purchase Inspection		<div>Classic Automobilia</div> <div>0425 250 613</div> <div>Maintenance, Modifications &amp; Restorations</div>					Auction Lot No			
Report No							Lot 33			
		ABN: 95 933 498 716			MVRL 38236					
Inspection Date	Make/Model				Year	Odometer - Mls / Km	VIN	Rating /5	4.5	
2/8/24	BMW Mini Cooper S				2002	11,799km	WMWRE32030TC65811	All values will be rounded down to the nearest 0.5		
		Overall Rating				Comments				
		1	1	1	1	0.5	Excellent original low milage vehicle.			
EXTERIOR		Good	Fair	Repair	N/C	N/A	Comments			
Presentation	✓									
Glass	✓									
Bodywork	✓									
Paintwork	✓						Paint chips on door edge.			
Lamps Condition	✓									
Bumper Bars	✓									
Brightwork	✓									
Seals	✓									
Convertible Roof						✓				
INTERIOR		Good	Fair	Repair	N/C	N/A	Comments			
Boot Area	✓									
Seats & Belts	✓									
Floor Coverings	✓									
Headlining/Visors	✓									
Trim	✓									
Doors	✓									
Windows and Mirrors	✓									
Heating and Ventilation	✓									
Lights/Wipers/Washers/Horn	✓									
Other Electrical	✓									
Entertainment Equipment	✓									
ABS/SRS	✓									
UNDERBODY		Good	Fair	Repair	N/C	N/A	Comments			
Structure	✓									
Corrosion	✓									
Powertrain	✓									
Exhaust	✓									
Brakes	✓									
Wheels & Tyres			✓				Rear tyres cracking. Tyres very old. Some gutter rash.			
Steering & Suspension	✓									
Fuel System	✓									
Fluid Leaks			✓				Oil leak from oil cooler area.			
										Pge 1/2
ENGINE BAY		Good	Fair	Repair	N/C	N/A	Comments			
Presentation	✓									
Fluid Levels/Condition	✓									
Cooling System	✓									
Power Steering	✓									
Electrical	✓									
Engine Running	✓		✓				Poor starting.			
Air Conditioning	✓									
ROAD TEST		Good	Fair	Repair	N/C	N/A	Comments			
Engine Performance	✓									
Transmission	✓									
Noise and Vibration	✓									
Steering and Suspension	✓									
Braking	✓									
Clutch	✓									
Instruments	✓									
General Comments										

Key																					
Good		Operational or well presented at time of inspection						U/S		Unservicable											
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure											
Repair		Requires repair, replacement or refurbishment						N/W		Not working											
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable											
★ ☆ ☆ ☆ ☆		Fluid escaping and dripping						N/C		Not checked											
★ ★ ☆ ☆ ☆																					
★ ★ ★ ☆ ☆		Vehicle requires substantial work or restoration																			
★ ★ ★ ★ ☆		Vehicle is in poor condition and in need of TLC																			
★ ★ ★ ★ ★		Vehicle is commensurate with age and useable																			
		Vehicle is in very good condition																			
		Vehicle is in excellent condition																			
Disclaimer																					
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																					
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																					
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																					
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																					
Page 2/2																					