					_ • _														
Pre-Purchase Inspection					SIC	Autor	nobii												
Report No					04	25 250 613				Auction Lot No									
		Maintenance, N				Modifications & Restorations			Lot 32										
		ABN: 95 933 498 716			716	MVRL 38236													
								Odo	neter -										
Inspection Date					Make/M	Mis / Km						Rating /5					5.0		
2/8/24				Toyo	ta Yaris	GR Rally	20	1,40	07km	JTDAF4E300A006890		All values v	s will be rounded down to the nearest 0.5						
		Ove	rall Rat	ting				Commen	ts										
	1	1	1	1	1		As new showroom condition.												
	-		-	-	_														
EXTERIOR	Good	Fair	Repair	N/C	N/A			Comment	s			Тур	oe 'a'	for ti	cks				
Presentation	~																		
Glass	✓																		
Bodywork	✓																		
Paintwork	~																		
Lamps Condition	~																		
Bumper Bars	✓																		
Brightwork					~														
	✓																		
Convertible Roof					✓														
INTERIOR	Good	Fair	Repair	N/C	N/A			Comment	s										
Boot Area	V																		
Seats & Belts	V																		
Floor Coverings	Y																		
Headlining/Visors	V																		
Trim	>																		
Doors Windows and Mirrors	V																		
Heating and Ventilation	•																		
	•																		
Other Electrical	•																		
Entertainment Equipment	~																		
ABS/SRS	~																		
UNDERBODY	Good	Fair	Repair	N/C	N/A			Comment	s										
Structure	✓																		
Corrosion	✓																		
Powertrain	✓																		
Exhaust	~																		
Brakes																			
Wheels & Tyres	>																		
Steering & Suspension Fuel System																			
Fluid Leaks	•																		
Traid Leaks	•									Pge 1/2									
										<u>-</u>									
ENGINE BAY	Good	Fair	Repair	N/C	N/A			Comment	s										
Presentation	✓		- Jewil	- 2 🗸				23VIII											
Fluid Levels/Condition	•																		
Cooling System	V																		
Power Steering	•																		
Electrical	~																		
Engine Running	✓																		
Air Conditioning	✓																		
ROAD TEST	Good	Fair	Repair	N/C	N/A			Comment	s										
Engine Performance	✓																		
Transmission	~																		
Noise and Vibration	✓																		
Steering and Suspension	~																		
Braking	✓																		
Clutch	~																		
Instruments	✓																		
						General Comments													

		Key								
Good Fair Repair Wetting	Operational or well present Commensurate for age of v Requires repair, replaceme Fluid escaping with the pot Fluid escaping and dripping	rehicle but has wear and to the or refurbishment ential to drip	ear	U/S N/S N/W N/A N/C	Unservicable Not secure Not working Not Applicable Not checked					
★ ★ ☆ ☆ ☆ ★ ★ ★ ☆ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ☆ ★ ★ ★ ★ ★	Vehicle requires substantia Vehicle is in poor condition Vehicle is commensurate w Vehicle is in very good cond	I work or restoration and in need of TLC rith age and useable								
	Vehicle is in excellent cond	ition Disclair	ner							
conclusively diagnosed. Classic Automobilia (MVRL38)	Road tests are conducted on log	responsible in regards to a purchase the	o 60Km/h. The value of the second sec	ehicle (nderbody was visually in	and any faults listed have not been spected on a vehicle hoist. ed influence to your decision to e(s) or any internal mechanica				
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection. Pge 2/2										