































Pre-Purchase Inspection		<div>Classic Automobiliæ</div> <div>0425 250 613</div> <div>Maintenance, Modifications & Restorations</div>					Auction Lot No	
Report No								
		ABN: 95 933 498 716					MVRL 38236	
Inspection Date	Make/Model					Year	Odometer - Mls / Km	VIN
27/2/25	Jaguar XJ-SC					1985	185,538km	SAJJNACY3CC126800
		Overall Rating				Comments		
		1	1	1	1	0.5	Great example for it's age.	
EXTERIOR		Good	Fair	Repair	N/C	N/A	Comments	
Presentation		✓						
Glass		✓						
Bodywork		✓					Driver's door poor fit.	
Paintwork		✓					Some small blistering and marks.	
Lamps Condition		✓						
Bumper Bars		✓						
Brightwork		✓						
Seals		✓						
Convertible Roof		✓					Some wear and fraying.	
INTERIOR		Good	Fair	Repair	N/C	N/A	Comments	
Boot Area		✓					Aged.	
Seats & Belts		✓						
Floor Coverings		✓						
Headlining/Visors			✓					
Trim		✓					Gear lever surround cracked.	
Doors		✓						
Windows and Mirrors				✓			Drivers door mirror N/W.	
Heating and Ventilation		✓						
Lights/Wipers/Washers/Horn		✓						
Other Electrical			✓				Some lights N/W.	
Entertainment Equipment							Not working.	
ABS/SRS						✓		
UNDERBODY		Good	Fair	Repair	N/C	N/A	Comments	
Structure		✓						
Corrosion		✓						
Powertrain		✓						
Exhaust				✓			Rear mufflers rusted.	
Brakes		✓						
Wheels & Tyres				✓			Wheels poor and tyres old.	
Steering & Suspension			✓				Aged and some boots slit.	
Fuel System		✓						
Fluid Leaks		✓					Engine wet.	
							Pge 1/2	
ENGINE BAY		Good	Fair	Repair	N/C	N/A	Comments	
Presentation		✓						
Fluid Levels/Condition		✓						
Cooling System		✓						
Power Steering		✓						
Electrical		✓						
Engine Running		✓						
Air Conditioning		✓						
ROAD TEST		Good	Fair	Repair	N/C	N/A	Comments	
Engine Performance		✓						
Transmission		✓						
Noise and Vibration		✓						
Steering and Suspension		✓						
Braking		✓						
Clutch						✓		
Instruments		✓						
General Comments								

Key																						
Good		Operational or well presented at time of inspection						U/S		Unservicable												
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure												
Repair		Requires repair, replacement or refurbishment						N/W		Not working												
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable												
    		Fluid escaping and dripping						N/C		Not checked												
    		Vehicle requires substantial work or restoration																				
    		Vehicle is in poor condition and in need of TLC																				
    		Vehicle is commensurate with age and useable																				
    		Vehicle is in very good condition																				
    		Vehicle is in excellent condition																				
Disclaimer																						
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																						
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																						
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																						
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																						
Page 2/2																						