































Pre-Purchase Inspection		<div>Classic Automobilia</div> <div>0425 250 613</div> <div>Maintenance, Modifications & Restorations</div>					Auction Lot No	
Report No								
		ABN: 95 933 498 716					MVRL 38236	
Inspection Date	Make/Model					Year	Odometer - Mls / Km	VIN
27/2/25	Morris Mini Cooper S					1970	44,484mls	YG2S4 1869
		Overall Rating				Comments		
		1	1	1	1	1	Would be hard to find better.	
EXTERIOR		Good	Fair	Repair	N/C	N/A	Comments	
Presentation	✓							
Glass	✓							
Bodywork	✓						Bonnet and door fit not perfect.	
Paintwork	✓						Small crack in bonnet paint. Some small blistering on seams. Some small imperfections.	
Lamps Condition	✓							
Bumper Bars	✓						Nudge bar has minor damage, R/H/S rear overrider dented.	
Brightwork	✓							
Seals			✓				Door seals torn.	
Convertible Roof					✓			
INTERIOR		Good	Fair	Repair	N/C	N/A	Comments	
Boot Area	✓						Belts aged.	
Seats & Belts	✓							
Floor Coverings	✓							
Headlining/Visors	✓							
Trim	✓							
Doors	✓							
Windows and Mirrors	✓							
Heating and Ventilation			✓				Heater lever N/W.	
Lights/Wipers/Washers/Horn	✓						Washers N/W.	
Other Electrical	✓							
Entertainment Equipment	✓							
ABS/SRS					✓			
UNDERBODY		Good	Fair	Repair	N/C	N/A	Comments	
Structure	✓							
Corrosion	✓							
Powertrain	✓							
Exhaust		✓					Hanger broken.	
Brakes	✓							
Wheels & Tyres			✓				Tyres 15 years old.	
Steering & Suspension			✓				Rear bump stops broken. Rubber components perished. Suspension low and sitting on bumpstops	
Fuel System	✓							
Fluid Leaks	✓						Engine wet.	
							Pge 1/2	
ENGINE BAY		Good	Fair	Repair	N/C	N/A	Comments	
Presentation	✓							
Fluid Levels/Condition	✓							
Cooling System	✓							
Power Steering					✓			
Electrical	✓							
Engine Running	✓							
Air Conditioning					✓			
ROAD TEST		Good	Fair	Repair	N/C	N/A	Comments	
Engine Performance	✓							
Transmission	✓							
Noise and Vibration	✓							
Steering and Suspension	✓							
Braking	✓							
Clutch	✓							
Instruments	✓							
General Comments								

Key																					
Good		Operational or well presented at time of inspection						U/S		Unservicable											
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure											
Repair		Requires repair, replacement or refurbishment						N/W		Not working											
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable											
    		Fluid escaping and dripping						N/C		Not checked											
    		Vehicle requires substantial work or restoration																			
    		Vehicle is in poor condition and in need of TLC																			
    		Vehicle is commensurate with age and useable																			
    		Vehicle is in very good condition																			
    		Vehicle is in excellent condition																			
Disclaimer																					
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																					
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																					
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																					
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																					
Page 2/2																					