































Key																						
Good		Operational or well presented at time of inspection						U/S		Unservicable												
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure												
Repair		Requires repair, replacement or refurbishment						N/W		Not working												
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable												
    		Fluid escaping and dripping						N/C		Not checked												
    		Vehicle requires substantial work or restoration																				
    		Vehicle is in poor condition and in need of TLC																				
    		Vehicle is commensurate with age and useable																				
    		Vehicle is in very good condition																				
    		Vehicle is in excellent condition																				
Disclaimer																						
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																						
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																						
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																						
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																						
Page 2/2																						