

Pre-Purchase Inspection

Report No

Classic Automobiliæ

0425 250 613

Maintenance, Modifications & Restorations

Auction Lot No

ABN: 95 933 498 716

MVRL 38236

Inspection Date

Make/Model

Year

Odometer - Mls / Km

VIN

45919

Mercedes 350SL

1973

182,871km

10704320010694

Overall Rating

Comments

1110.50

Mechanically very good.

Rating /5

3.5

All values will be rounded down to the nearest 0.5

EXTERIOR

GoodFairRepairN/CN/A

Comments

Presentation

✓

Glass

✓

Windscreen scratched.

Bodywork

✓

Poor panel fit. Evidence of rust repairs.

Paintwork

✓

Some areas of poor paint, inc. minor blister on bonnet and repairs.

Lamps Condition

✓

Bumper Bars

✓

Poor fit and rubber trim.

Brightwork

✓

Seals

✓

Convertible Roof

✓

INTERIOR

GoodFairRepairN/CN/A

Comments

Boot Area

✓

Boot light missing.

Seats & Belts

✓

Floor Coverings

✓

Headlining/Visors

✓

Sun visors puffy.

Trim

✓

Showing wear and some ageing.

Doors

✓

Windows and Mirrors

✓

Heating and Ventilation

✓

Lights/Wipers/Washers/Horn

✓

Other Electrical

✓

Entertainment Equipment

✓

ABS/SRS

✓

UNDERBODY

GoodFairRepairN/CN/A

Comments

Structure

✓

Corrosion

✓

Evidence of some rust repairs.

Powertrain

✓

Exhaust

✓

Brakes

✓

Wheels & Tyres

✓

Steering & Suspension

✓

Fuel System

✓

Fluid Leaks

✓

ENGINE BAY

GoodFairRepairN/CN/A

Comments

Presentation

✓

Fluid Levels/Condition

✓

Cooling System

✓

Power Steering

✓

Electrical

✓

Engine Running

✓

Air Conditioning

✓

ROAD TEST

GoodFairRepairN/CN/A

Comments

Engine Performance

✓

Transmission

✓

Noise and Vibration

✓

Steering and Suspension

✓

Steering vague.

Braking

✓

Clutch

✓

Instruments

✓

Clock N/W.

General Comments

Type 'a' for ticks

Pge 1/2

1

Key																					
Good		Operational or well presented at time of inspection						U/S		Unservicable											
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure											
Repair		Requires repair, replacement or refurbishment						N/W		Not working											
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable											
    		Fluid escaping and dripping						N/C		Not checked											
    		Vehicle requires substantial work or restoration																			
    		Vehicle is in poor condition and in need of TLC																			
    		Vehicle is commensurate with age and useable																			
    		Vehicle is in very good condition																			
    		Vehicle is in excellent condition																			
Disclaimer																					
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																					
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																					
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																					
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																					
Page 2/2																					