

Pre-Purchase Inspection		Classic Automobilia 0425 250 613 Maintenance, Modifications & Restorations					Auction Lot No			
Report No										
ABN: 95 933 498 716		MVRL 38236								
Inspection Date	Make/Model					Year	Odometer - Mls / Km	VIN	Rating /5	3.5
45979	Bentley T-Series					1967	13,406mls	SBH2025	All values will be rounded down to the nearest 0.5	
Overall Rating		Comments								
1	1	1	0.5	0	Mechanically excellent and a very sound vehicle.					
EXTERIOR		Good	Fair	Repair	N/C	N/A	Comments			
Presentation		✓								
Glass	✓									
Bodywork	✓						Some rust appearing in blisters on rear lower valances.			
Paintwork		✓					Paint is poor flat and faded.			
Lamps Condition	✓									
Bumper Bars		✓								
Brightwork	✓									
Seals		✓								
Convertible Roof					✓					
INTERIOR		Good	Fair	Repair	N/C	N/A	Comments			
Boot Area		✓								
Seats & Belts		✓								
Floor Coverings		✓								
Headlining/Visors	✓									
Trim		✓					Trim and woodwork aged.			
Doors	✓									
Windows and Mirrors	✓									
Heating and Ventilation			✓				Fan motor noisy when operating.			
Lights/Wipers/Washers/Horn	✓									
Other Electrical		✓								
Entertainment Equipment			✓				Not working.			
ABS/SRS					✓					
UNDERBODY		Good	Fair	Repair	N/C	N/A	Comments			
Structure	✓									
Corrosion	✓									
Powertrain	✓									
Exhaust	✓									
Brakes	✓									
Wheels & Tyres	✓									
Steering & Suspension	✓									
Fuel System	✓									
Fluid Leaks	✓									
							Pge 1/2			
ENGINE BAY		Good	Fair	Repair	N/C	N/A	Comments			
Presentation	✓									
Fluid Levels/Condition	✓									
Cooling System	✓									
Power Steering	✓									
Electrical	✓									
Engine Running	✓									
Air Conditioning			✓				Not working.			
ROAD TEST		Good	Fair	Repair	N/C	N/A	Comments			
Engine Performance	✓									
Transmission	✓									
Noise and Vibration	✓									
Steering and Suspension	✓									
Braking	✓									
Clutch					✓					
Instruments		✓					Clock and fuel gauge N/W.			
General Comments										

Key																						
Good		Operational or well presented at time of inspection						U/S		Unservicable												
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure												
Repair		Requires repair, replacement or refurbishment						N/W		Not working												
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable												
    		Fluid escaping and dripping						N/C		Not checked												
    		Vehicle requires substantial work or restoration																				
    		Vehicle is in poor condition and in need of TLC																				
    		Vehicle is commensurate with age and useable																				
    		Vehicle is in very good condition																				
    		Vehicle is in excellent condition																				
Disclaimer																						
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																						
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																						
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																						
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																						
Page 2/2																						