

Pre-Purchase Inspection

Report No

Classic Automobilia

0425 250 613

Maintenance, Modifications & Restorations

Auction Lot No

ABN: 95 933 498 716

MVRL 38236

Inspection Date

45982

Make/Model

Jaguar MkIV

Year

1948

Odometer - Mls / Km

98,966mls

VIN

510848

Overall Rating

1110.50

Comments

Very solid vehicle let down by paint and trim.

Rating /5

3.5

All values will be rounded down to the nearest 0.5

EXTERIOR

GoodFairRepairN/CN/A

Comments

Presentation

Glass

Bodywork

Paintwork

Lamps Condition

Bumper Bars

Brightwork

Seals

Convertible Roof

INTERIOR

GoodFairRepairN/CN/A

Comments

Boot Area

Seats & Belts

Floor Coverings

Headlining/Visors

Trim

Doors

Windows and Mirrors

Heating and Ventilation

Lights/Wipers/Washers/Horn

Other Electrical

Entertainment Equipment

ABS/SRS

UNDERBODY

GoodFairRepairN/CN/A

Comments

Structure

Corrosion

Powertrain

Exhaust

Brakes

Wheels & Tyres

Steering & Suspension

Fuel System

Fluid Leaks

ENGINE BAY

GoodFairRepairN/CN/A

Comments

Presentation

Fluid Levels/Condition

Cooling System

Power Steering

Electrical

Engine Running

Air Conditioning

ROAD TEST

GoodFairRepairN/CN/A

Comments

Engine Performance

Transmission

Noise and Vibration

Steering and Suspension

Braking

Clutch

Instruments

General Comments

Type 'a' for ticks

Pge 1/2

Key																					
Good		Operational or well presented at time of inspection						U/S		Unservicable											
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure											
Repair		Requires repair, replacement or refurbishment						N/W		Not working											
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable											
    		Fluid escaping and dripping						N/C		Not checked											
    		Vehicle requires substantial work or restoration																			
    		Vehicle is in poor condition and in need of TLC																			
    		Vehicle is commensurate with age and useable																			
    		Vehicle is in very good condition																			
    		Vehicle is in excellent condition																			
Disclaimer																					
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																					
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																					
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																					
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																					
Page 2/2																					