

Pre-Purchase Inspection

Report No

Classic Automobilia

0425 250 613

Maintenance, Modifications & Restorations

Auction Lot No

ABN: 95 933 498 716

MVRL 38236

Inspection Date

45979

Make/Model

Jaguar XK140

Year

1955

Odometer - Mls / Km

26,366mls

VIN

A814021DN

Overall Rating

11110.5

Comments

Excellent recently restored vehicle.

Rating /5

4.5

All values will be rounded down to the nearest 0.5

EXTERIOR

GoodFairRepairN/CN/A

Comments

Presentation

✓

Glass

✓

Bodywork

✓

Paintwork

✓

Paint has many chips, marks and imperfections.

Lamps Condition

✓

Bumper Bars

✓

Brightwork

✓

Seals

✓

Some seals have come unglued.

Convertible Roof

✓

INTERIOR

GoodFairRepairN/CN/A

Comments

Boot Area

✓

Seats & Belts

✓

Floor Coverings

✓

Headlining/Visors

✓

Trim

✓

Trim is a bit untidy and poorly finished in areas.

Doors

✓

Windows and Mirrors

✓

✓

L/H window stiff to operate. Wood on door distorted. L/H rear window mechanism broken.

Heating and Ventilation

✓

Lights/Wipers/Washers/Horn

✓

Headlamps not working on high beam. L/H wiper N/W.

Other Electrical

✓

Entertainment Equipment

✓

ABS/SRS

✓

UNDERBODY

GoodFairRepairN/CN/A

Comments

Structure

✓

Corrosion

✓

Powertrain

✓

Exhaust

✓

R/H tail pipe scraped.

Brakes

✓

Wheels & Tyres

✓

Tyres are 15 years old. Rust on wheel spokes, suspect from flex rubbing.

Steering & Suspension

✓

Fuel System

✓

Fluid Leaks

✓

✓

Overdrive leaking quite badly.

ENGINE BAY

GoodFairRepairN/CN/A

Comments

Presentation

✓

Fluid Levels/Condition

✓

Cooling System

✓

Power Steering

✓

Electrical

✓

Engine Running

✓

Air Conditioning

✓

ROAD TEST

GoodFairRepairN/CN/A

Comments

Engine Performance

✓

Transmission

✓

Syncros are very poor. Overdrive not operating correctly.

Noise and Vibration

✓

Steering and Suspension

✓

✓

Adjustable steering shaft does not lock.

Braking

✓

Clutch

✓

Instruments

✓

Clock N/W.

General Comments

Type 'a' for ticks

Pge 1/2

1

Key																					
Good		Operational or well presented at time of inspection						U/S		Unservicable											
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure											
Repair		Requires repair, replacement or refurbishment						N/W		Not working											
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable											
    		Fluid escaping and dripping						N/C		Not checked											
    		Vehicle requires substantial work or restoration																			
    		Vehicle is in poor condition and in need of TLC																			
    		Vehicle is commensurate with age and useable																			
    		Vehicle is in very good condition																			
    		Vehicle is in excellent condition																			
Disclaimer																					
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																					
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																					
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																					
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																					
Page 2/2																					