

Observation Report		Classic Automobilia 0425 250 613 Maintenance, Modifications & Restorations					Auction Lot No	
Report No								
		ABN: 95 933 498 716					MVRL 38236	
Inspection Date	Make/Model					Year	Odometer - Mls / Km	VIN
46069	Chrysler 300K					1964	83,367mls	8443217985
		Overall Rating				Comments		
		1	1	0	0	0	Requires work.	
EXTERIOR		Good	Fair	Repair	N/C	N/A	Comments	
Presentation			✓					
Glass			✓					
Bodywork			✓				Areas of corrosion and poor finish.	
Paintwork			✓				Chips, imperfections, blisters and poor in areas.	
Lamps Condition			✓					
Bumper Bars			✓					
Brightwork			✓				Tarnished and blistering.	
Seals				✓			Old and perished.	
Convertible Roof						✓		
INTERIOR		Good	Fair	Repair	N/C	N/A	Comments	
Boot Area			✓					
Seats & Belts			✓					
Floor Coverings			✓					
Headlining/Visors			✓				Visors torn.	
Trim			✓				Dash top torn and distorted. Steering wheel broken.	
Doors			✓				Door trims poor.	
Windows and Mirrors			✓	✓			Passenger winow electric N/W.	
Heating and Ventilation			✓					
Lights/Wipers/Washers/Horn		✓						
Other Electrical			✓					
Entertainment Equipment				✓			Radio N/W.	
ABS/SRS						✓		
UNDERBODY		Good	Fair	Repair	N/C	N/A	Comments	
Structure				✓			Advanced corrosion with holes in both sills.	
Corrosion				✓			See above. Evidence of previouir rust repairs in areas. Bottoms of doors rusty. Several corrosion blisters in paint.	
Powertrain		✓						
Exhaust		✓						
Brakes		✓						
Wheels & Tyres			✓				Tyres 10 years old.	
Steering & Suspension				✓			Suspension components badly worn and perished. Rear spring shackles bottomed out. Suspension low. Excessive steering play.	
Fuel System		✓						
Fluid Leaks			✓				Transmission dripping oil. Engine sump dented.	
							Pge 1/2	
ENGINE BAY		Good	Fair	Repair	N/C	N/A	Comments	
Presentation			✓					
Fluid Levels/Condition			✓					
Cooling System			✓				Lower radiator hose blistered from power steering leak.	
Power Steering				✓			Pump leaking.	
Electrical				✓			Battery N/S.	
Engine Running		✓						
Air Conditioning						✓		
ROAD TEST		Good	Fair	Repair	N/C	N/A	Comments	
Engine Performance		✓						
Transmission		✓						
Noise and Vibration				✓			Clunks and groans.	
Steering and Suspension				✓			Clunks and wanders.	
Braking			✓					
Clutch						✓		
Instruments				✓			Clock, speedometer, econo gauge and oil lamp N/W.	
General Comments								

Key																					
Good		Operational or well presented at time of inspection						U/S		Unservicable											
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure											
Repair		Requires repair, replacement or refurbishment						N/W		Not working											
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable											
    		Fluid escaping and dripping						N/C		Not checked											
    		Vehicle requires substantial work or restoration																			
    		Vehicle is in poor condition and in need of TLC																			
    		Vehicle is commensurate with age and useable																			
    		Vehicle is in very good condition																			
    		Vehicle is in excellent condition																			
Disclaimer																					
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																					
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																					
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																					
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																					
Page 2/2																					