

Observation Report

Report No

Auction Lot No

Classic Automobilia

0425 250 613

Maintenance, Modifications & Restorations

ABN: 95 933 498 716

MVRL 38236

Inspection Date

Make/Model

Year

Odometer - Mls / Km

VIN

46069

Ford Mustang

1965

2,220mls

5R07C149633

Overall Rating

Comments

11100

Good car with lots of upgrades but few things need attention.

Rating /5

3.0

All values will be rounded down to the nearest 0.5

EXTERIOR

GoodFairRepairN/CN/A

Comments

Presentation

✓

Glass

✓

Bodywork

✓

Poor fit and finish and some panels need securing. Ripples and dents L/H side.

Paintwork

✓

Poor preparation and flat finish on paintwork, some minor overspray on sill trim near driver's door iam

Lamps Condition

✓

Bumper Bars

✓

Brightwork

✓

Seals

✓

Convertible Roof

✓

INTERIOR

GoodFairRepairN/CN/A

Comments

Boot Area

✓

Spare wheel missing, untidy finish.

Seats & Belts

✓

Floor Coverings

✓

Headlining/Visors

✓

Trim

✓

Doors

✓

Drivers check strap noisy.

Windows and Mirrors

✓

Heating and Ventilation

✓

Ventilation fan N/W.

Lights/Wipers/Washers/Horn

✓

Indicators cancel when steering wheel moved, Horn N/W. Washers N/W.

Other Electrical

✓

Entertainment Equipment

✓

Antenna broken.

ABS/SRS

✓

UNDERBODY

GoodFairRepairN/CN/A

Comments

Structure

✓

Both floorpans have been replaced and not welded to chassis rails. Both floorpans badly dented from jacking L/H chassis rail dented

Corrosion

✓

Powertrain

✓

Front propshaft uni joint U/S.

Exhaust

✓

Brakes

✓

Wheels & Tyres

✓

Tyres 12 years old, some minor kerb rash on rims.

Steering & Suspension

✓

Rubber components perished and aged. L/H/F shock N/W and clunk when bouncing. Some components aged

Fuel System

✓

Fluid Leaks

✓

Engine and transmission leaking.

ENGINE BAY

GoodFairRepairN/CN/A

Comments

Presentation

✓

Fluid Levels/Condition

✓

Cooling System

✓

Power Steering

✓

Electrical

✓

Battery N/S and undersize.

Engine Running

✓

Puffing noise from R/H exhaust manifold area.

Air Conditioning

✓

Not cold due to depleted refrigerant and vent fan noisy.

ROAD TEST

GoodFairRepairN/CN/A

Comments

Engine Performance

✓

Transmission

✓

Noise and Vibration

✓

Steering and Suspension

✓

Braking

✓

Brake proportioning needs adjusting, locks rear brakes.

Clutch

✓

Instruments

✓

Oil pressure and temperature gauges not indicating.

General Comments

1

Key																						
Good		Operational or well presented at time of inspection						U/S		Unservicable												
Fair		Commensurate for age of vehicle but has wear and tear						N/S		Not secure												
Repair		Requires repair, replacement or refurbishment						N/W		Not working												
Wetting		Fluid escaping with the potential to drip						N/A		Not Applicable												
    		Fluid escaping and dripping						N/C		Not checked												
    		Vehicle requires substantial work or restoration																				
    		Vehicle is in poor condition and in need of TLC																				
    		Vehicle is commensurate with age and useable																				
    		Vehicle is in very good condition																				
    		Vehicle is in excellent condition																				
Disclaimer																						
This is a visual inspection only carried out by Classic Automobilia (MVRL38236). No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.																						
Classic Automobilia (MVRL38236) will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.																						
The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal mechanical components.																						
This pre-purchase inspection report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.																						
Page 2/2																						