

# Vehicle Observation Report



**Lot No. 4**

|                     |                      |          |       |              |             |  |       |
|---------------------|----------------------|----------|-------|--------------|-------------|--|-------|
| Description :       | Citreon 2CV6 Special |          |       | Colour :     | Red         |  |       |
| Chassis No. / VIN : | VF7AZKA00KA246403    |          | PHOTO | Engine No :  | 906012900   |  | PHOTO |
|                     |                      |          | Y     |              |             |  | Y     |
|                     | N/A                  |          |       |              | Not sighted |  |       |
|                     | 75268-H              | C.P. VIC | Y     |              | Current     |  | Y     |
| Odometer :          | 81674m               |          | Y     | Fuel level : | 1/4         |  |       |

| Item             | ✓ / X | Details                                                              | PHOTO |
|------------------|-------|----------------------------------------------------------------------|-------|
| PAINT            | X     | Bonnet paint very thin, needs repaint.                               | Y     |
| PANEL            | X     | Minor scratches in numerous locations, rust spot LHR window surround | Y     |
| GLASS            | ✓     |                                                                      |       |
| CHROME / TRIM    | X     | Loose trim leading edge of drivers door.                             | Y     |
| WHEELS / TYRES   | ✓     |                                                                      |       |
| TOOLS            | ✓     |                                                                      |       |
| BUMPERS          | X     | Front and rear bumpers chipped and scratched.                        | Y     |
| SOFT / HARD TOP  | ✓     |                                                                      |       |
| INTERIOR         | ✓     |                                                                      | Y     |
| BOOT / LOAD AREA | X     | see 'Additional comments'                                            | Y     |
| ENGINE BAY       | ✓     |                                                                      |       |
| LIGHTS           | ✓     |                                                                      | Y     |
| HORN             | ✓     |                                                                      |       |
| HEATER / A/C     | ✓     | No A/C                                                               |       |
| WIPER / WASHER   | ✓     |                                                                      |       |
| KEYS / SPARES    | ✓     |                                                                      |       |
| BOOKS            | X     | No books, some receipts                                              | Y     |
| ACCESSORIES      | ✓     | Luggage rack and headlight shields fitted.                           | Y     |
| SPARE PARTS      | X     | No spares                                                            |       |
| ENGINE RUNS      | ✓     | Engine runs well.                                                    |       |
| DRIVES           | X     | Not road tested                                                      |       |
|                  |       |                                                                      |       |

### Additional Comments

Modern headunit with large front speakers and additional very large sub woofer fitted which takes up most of the boot space, all in working order.

|                |        |            |
|----------------|--------|------------|
| INSPECTED BY : | DATE : | 11/09/2026 |
|----------------|--------|------------|