

Vehicle Observation Report



Lot No. 10

Description :

		PHOTO
Chassis No. / VIN :	ZFA3120000J605991	Y
Body No :	N/A	
Rego / State :	DVC-710VIC	Y
Odometer :	41379Km	Y

Colour: White

		PHOTO
Engine No :	312A30002108518	
Trans No. :	N/A	
Last Reg Date:	Current	Y
Fuel level :	1/3	Y

Item	✓ / X	Details	PHOTO
PAINT	X	Scuff mark under front left bumper	Y
PANEL	✓		
GLASS	✓		
CHROME / TRIM	✓		
WHEELS / TYRES	✓		
TOOLS	✓		
BUMPERS	✓		
SOFT / HARD TOP	N/A		
INTERIOR	X	Some scratches on seat backs and gear lever knob.	Y
BOOT / LOAD AREA	✓		
ENGINE BAY	✓		
LIGHTS	✓		
HORN	✓		
HEATER / A/C	✓		
WIPER / WASHER	✓		
KEYS / SPARES	✓		
BOOKS	✓		Y
ACCESSORIES	N/A		
SPARE PARTS	X	No spare parts	
ENGINE RUNS	✓		
DRIVES	✓	see 'Additional Comments'	

Additional Comments

Dives well, new brake pads and rotors recently fitted. RWC supplied on sale

INSPECTED BY :	DATE :	11/09/2026
----------------	--------	------------