Vehicle Observation Report

Donington AUCTIONS & SALES

Lot No.

Description : Bentley S2 Continental DHC **Colour :** Green

			PHOTO			PHOTO
Chassis No. / VIN :	BC69BY		Y	**Engine No :**	P3036	
Body No :				**Trans No. :**		
Rego / State :	0636-H0	VIC C.P.	Y	**Last Reg Date:**	Current	Y
Odometer :	23241m		Y	**Fuel level :**		

Item	✓ / X	Details	PHOTO
PAINT	X	Chips around boot lid, flaking under rear number plate, dry areas LHR guard.	Y
PANEL	✓		
GLASS	X	Minor delamination top centre of windscreen, electric windows intermittent in operation.	Y
CHROME / TRIM	✓		
WHEELS / TYRES	✓		
TOOLS	✓		
BUMPERS	X	Chrome pitting on both bumpers.	
SOFT / HARD TOP	X	Small tears on lower sides, rear screen scratched.	Y
INTERIOR	✓	Seats re-trimmed.	Y
BOOT / LOAD AREA	✓		
ENGINE BAY	✓		
LIGHTS	X	RHR turn indicator not working, Dip switch works intermittently.	
HORN	✓		
HEATER / A/C	X	No A/C	
WIPER / WASHER	✓		
KEYS / SPARES	✓		
BOOKS	✓	see "Vehicle Description"	
ACCESSORIES	X		
SPARE PARTS	X		
ENGINE RUNS	X	Needs attention to cold start, runs very rich on start up.	
DRIVES	X	Brake servo needs attention, brakes week at slow speed.	

Additional Comments

INSPECTED BY : **DATE :** 9/11/2026