Vehicle Observation Report

Donington AUCTIONS & SALES

Lot No.

Description : 1974 Jaguar Series II XJ6L **Colour :** Brown

			PHOTO			PHOTO
Chassis No. / VIN :	2T 3137 BW		Y	**Engine No :**	7L 95152	
Body No :	5T 1828			**Trans No. :**	015 11791	
Rego / State :	10689-H	VIC C.P.	Y	**Last Reg Date:**	2/11/2022	
Odometer :	65640km		Y	**Fuel level :**		

Item	✓ / X	Details	PHOTO
PAINT	X	Flaking paint on LHF guard, general paint condition poor.	Y
PANEL	✓		
GLASS	X	LHR window water stained.	Y
CHROME / TRIM	X	Window surrounds showing signs of corrosion	Y
WHEELS / TYRES	✓		
TOOLS	✓		
BUMPERS	X	Pitting and corrosion both bumpers.	Y
SOFT / HARD TOP	N/A		
INTERIOR	X	Drivers door armrest cracking	Y
BOOT / LOAD AREA	✓		
ENGINE BAY	✓		
LIGHTS	✓		
HORN	✓		
HEATER / A/C	X	A/C not working	
WIPER / WASHER	X	Washers not working	
KEYS / SPARES	✓		
BOOKS	✓		
ACCESSORIES	X		
SPARE PARTS	X		
ENGINE RUNS	✓		
DRIVES	✓		

Additional Comments

New battery fitted

INSPECTED BY : **DATE :** 9/11/2026