Vehicle Observation Report

Donington AUCTIONS & SALES

Lot No.

Description : Lagonda M45 Martin & King sedan **Colour :** Brown/Cream

		PHOTO			PHOTO
Chassis No. / VIN :	Z11369	Y	**Engine No :**	3118	Y
Body No :			**Trans No. :**		
Rego / State :		Y	**Last Reg Date:**		Y
Odometer :	94204m	Y	**Fuel level :**	Low	

Item	✓ / X	Details	PHOTO
PAINT	X	Blistering and dry areas, generally poor condition.	Y
PANEL	X	Cracks around base of 'A'pillars.	Y
GLASS	X	Crazing on side windows.	Y
CHROME / TRIM			
WHEELS / TYRES			
TOOLS			
BUMPERS	X	Chrome tarnished on both bumpers.	
SOFT / HARD TOP	N/A		
INTERIOR	X	Seats and carpets heavily worn, appear to be original.	Y
BOOT / LOAD AREA	✓		
ENGINE BAY	✓		
LIGHTS	X	LH headlamp, front park lights and LH tail light not working, LH trafficator broken.	Y
HORN	✓		
HEATER / A/C	✓	Heater works, No A/C fitted.	
WIPER / WASHER	X	No washers fitted, wiper blade torn,	
KEYS / SPARES	X	No keys	
BOOKS	✓	see "Vehicle Description".	
ACCESSORIES	X		
SPARE PARTS	X		
ENGINE RUNS	✓	Front carburetter leaking fuel.	
DRIVES	✓		

Additional Comments

Rear bumper may not be original as boot doesn't fully open.

INSPECTED BY : **DATE :** 9/11/2026