Observation Report

Report No

Donington AUCTIONS & SALES

Auction Lot No
1

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
November 23,2026	Range Rover Classic	1978	2879 km	35639762F

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✓				Well-used condition with some wear and tear
Glass		✓				Scratched in places
Bodywork		✓				Some rust repairs evident; rust at base of pass. door & base of upper tailgate, some rust in one patch on roof turret
Paintwork		✓				A number if repairs & touch ups , particularly at the rear
Lamps Condition		✓				
Bumper Bars		✓				
Brightwork					✓	
Seals		✓				
Convertible Roof					✓	

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area		✓				
Seats & Belts		✓				
Floor Coverings		✓				
Headlining/Visors		✓				
Trim		✓				
Doors		✓				
Windows and Mirrors		✓				
Heating and Ventilation			✓			A/C not working
Lights/Wipers/Washers/Horn		✓				
Other Electrical		✓				
Entertainment Equipment					✓	
ABS/SRS					✓	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure	✓					
Corrosion		✓				Nil Observed
Powertrain		✓				
Exhaust		✓				
Brakes			✓			LHF brake coated in oil
Wheels & Tyres		✓				2023 - both front tyres worn, wheels poorly painted in gold
Steering & Suspension		✓				
Fuel System						
Fluid Leaks			✓			Front diff leaking onto LHF brake

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✓				
Fluid Levels/Condition		✓				
Cooling System						Engine coolant Temp indicates running cold
Power Steering		✓				
Electrical		✓				
Engine Running		✓				
Air Conditioning			✓			

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments

Engine Performance		✓				
Transmission		✓				Selector gate detent worn & backlash in driveline
Noise and Vibration		✓				Has some transmission whine
Steering and Suspension		✓				
Braking		✓				
Clutch		✓				Shudders
Instruments		✓				

Key

Good	Operational or well presented at time of inspection	**U/S**	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	**N/S**	Not secure
Repair	Requires repair, replacement or refurbishment	**N/W**	Not working
Wetting	Fluid escaping with the potential to drip	**N/A**	Not Applicable
Leaking	Fluid escaping and dripping	**N/C**	Not checked

Disclaimer

This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.

Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal

This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.