Observation Report

Report No

Donington AUCTIONS & SALES

Auction Lot No
11

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
24 November, 2026	Reliant Scimitar GTE	1972	3866mi	93/1246

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✔				Rough exterior but in reasonable shape otherwise
Glass		✔				Sratched in places
Bodywork		✔				Fibreglass broken on both front wheelarches
Paintwork			✔			Older poor quality respray, peeling in places
Lamps Condition		✔				
Bumper Bars		✔				Some light surface rust, rear bumper bent in places
Brightwork		✔				
Seals		✔				
Convertible Roof					✔	

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area	✔					
Seats & Belts	✔					
Floor Coverings	✔					
Headlining/Visors	✔					
Trim		✔				Gearshift boot n/s
Doors		✔				
Windows and Mirrors			✔			LH window n/w
Heating and Ventilation				✔		
Lights/Wipers/Washers/Horn			✔			Brake lights n/w
Other Electrical		✔				
Entertainment Equipment					✔	Radio missing
ABS/SRS					✔	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure	✔					
Corrosion	✔					
Powertrain	✔					
Exhaust	✔					
Brakes	✔					
Wheels & Tyres	✔					Tyres dated 30-2022
Steering & Suspension	✔					
Fuel System		✔				
Fluid Leaks		✔				Seepage observed from Laycock Overdrive unit

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✔				
Fluid Levels/Condition		✔				
Cooling System		✔				
Power Steering					✔	

Electrical		✔				
Engine Running	✔					
Air Conditioning					✔	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance	✔					
Transmission		✔				Selector could use some TLC
Noise and Vibration		✔				
Steering and Suspension			✔			Rear shock absorbers worn
Braking	✔					
Clutch	✔					
Instruments	✔					

Key

Good	Operational or well presented at time of inspection	**U/S**	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	**N/S**	Not secure
Repair	Requires repair, replacement or refurbishment	**N/W**	Not working
Wetting	Fluid escaping with the potential to drip	**N/A**	Not Applicable
Leaking	Fluid escaping and dripping	**N/C**	Not checked

Disclaimer

This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal

This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.