Observation Report

Report No

Donington AUCTIONS & SALES

Auction Lot No
13

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
24 November, 2026	Fiat X1/9	1980	100234km	128AS.0115934

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✔					
Glass	✔					
Bodywork		✔				Small patch of corrosion on RHR quarter panel
Paintwork		✔				Older respray with a few scratches, touchups evident
Lamps Condition		✔				
Bumper Bars		✔				Trim moulding on rear bumper bar n/s
Brightwork		✔				
Seals		✔				
Convertible Roof	✔					

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area		✔				
Seats & Belts	✔					
Floor Coverings	✔					
Headlining/Visors	✔					
Trim		✔				
Doors		✔				Aftermarket speakers added to door panels
Windows and Mirrors		✔				
Heating and Ventilation		✔				
Lights/Wipers/Washers/Horn				✔		Front parker lights n/w
Other Electrical		✔				
Entertainment Equipment			✔			Radio n/w
ABS/SRS					✔	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure	✔					
Corrosion		✔				
Powertrain		✔				
Exhaust		✔				
Brakes		✔				Rear caliper binding
Wheels & Tyres			✔			Tyres dated 37-2006 - cracked & need replacement
Steering & Suspension		✔				
Fuel System		✔				
Fluid Leaks		✔				

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✔				
Fluid Levels/Condition		✔				
Cooling System	✔					
Power Steering					✔	

Electrical		✔				
Engine Running		✔				
Air Conditioning					✔	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance		✔				Could use an engine tune
Transmission		✔				
Noise and Vibration		✔				
Steering and Suspension		✔				
Braking			✔			RHR brake caliper binding
Clutch	✔					
Instruments	✔					

Key

Good	Operational or well presented at time of inspection	**U/S**	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	**N/S**	Not secure
Repair	Requires repair, replacement or refurbishment	**N/W**	Not working
Wetting	Fluid escaping with the potential to drip	**N/A**	Not Applicable
Leaking	Fluid escaping and dripping	**N/C**	Not checked

Disclaimer

This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal

This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.