A2:M10A2:M11G5A2:N79

Observation Report

Report No

Donington AUCTIONS & SALES

Auction Lot No
14

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
November 24,2026	Alfa Romeo SZ	1990	90831km	ZAR16200003000063

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✓				Showing some age
Glass		✓				
Bodywork		✓				Sun damage on carbon rear spoiler
Paintwork		✓				
Lamps Condition		✓				
Bumper Bars		✓				
Brightwork					✓	
Seals		✓				
Convertible Roof					✓	

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area				✓		
Seats & Belts	✓					
Floor Coverings	✓					
Headlining/Visors	✓					
Trim			✓			Glovebox catch broken
Doors		✓				
Windows and Mirrors		✓				Power window opertation slow
Heating and Ventilation				✓		
Lights/Wipers/Washers/Horn		✓				
Other Electrical		✓				
Entertainment Equipment				✓		
ABS/SRS					✓	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure		✓				
Corrosion		✓				Surface rust evident in places
Powertrain			✓			Noisy transaxle
Exhaust			✓			Exhaust system holed
Brakes		✓				
Wheels & Tyres		✓				Tyres dated 04/2025
Steering & Suspension			✓			Rear suspension A-frame bushes perished , adjustable struts n/w
Fuel System		✓				
Fluid Leaks		✓				

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✓				
Fluid Levels/Condition		✓				Coolant low
Cooling System		✓				
Power Steering		✓				
Electrical			✓			Alternator n/w
Engine Running			✓			Running on 5 cyclinders, RH inlet cam out of phase
Air Conditioning				✓		

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments

Engine Performance			✓			
Transmission		✓				
Noise and Vibration			✓			
Steering and Suspension			✓			Adjustable suspension n/w
Braking		✓				
Clutch		✓				
Instruments		✓				

Key

Good	Operational or well presented at time of inspection	**U/S**	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	**N/S**	Not secure
Repair	Requires repair, replacement or refurbishment	**N/W**	Not working
Wetting	Fluid escaping with the potential to drip	**N/A**	Not Applicable
Leaking	Fluid escaping and dripping	**N/C**	Not checked

Disclaimer

This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist.

Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal

This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.