Observation Report

Report No

Donington AUCTIONS & SALES

Auction Lot No
2

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
23 November 2026	Volkswagen Golf GTi	1982	110731m	WVWZZZ17ZDW14

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✔				
Glass		✔				Some scratches, passenger side door glass missing
Bodywork		✔				Poor panel fit, small dents evident, rear valance bent
Paintwork		✔				Lots of scratches, stone chips
Lamps Condition		✔				Rear lamps smoked
Bumper Bars		✔				Poor fitment
Brightwork					✔	
Seals			✔			Minor leaks from sunroof
Convertible Roof					✔	

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area		✔				Missing inner trim on rear beaver panel
Seats & Belts		✔				Passenger seat n/s, cloth has few tears & small holes
Floor Coverings		✔				
Headlining/Visors		✔				
Trim		✔				
Doors		✔				LHS door trim has a tear
Windows and Mirrors		✔				
Heating and Ventilation				✔		
Lights/Wipers/Washers/Horn		✔				
Other Electrical			✔			Some gauges not working
Entertainment Equipment				✔		Aftermarket C/D player
ABS/SRS					✔	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure		✔				Evidence of prior corrosion repairs
Corrosion		✔				Some pitting & surface rust evident
Powertrain		✔				
Exhaust		✔				
Brakes		✔				
Wheels & Tyres	✔					Tyre date 44-2021, slow leak in RHR tyre
Steering & Suspension		✔				
Fuel System			✔			Fuel leak at divider head
Fluid Leaks			✔			

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation			✔			
Fluid Levels/Condition		✔				Leaking fuel from divider
Cooling System		✔				
Power Steering					✔	

Electrical			✔			Stop & parking lights n/w
Engine Running			✔			Air leaks, engine running poorly
Air Conditioning					✔	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance		✔				Needs some recommissioning before serious use
Transmission		✔				
Noise and Vibration			✔			
Steering and Suspension		✔				
Braking		✔				
Clutch		✔				
Instruments		✔				

Key

Good	Operational or well presented at time of inspection	**U/S**	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	**N/S**	Not secure
Repair	Requires repair, replacement or refurbishment	**N/W**	Not working
Wetting	Fluid escaping with the potential to drip	**N/A**	Not Applicable
Leaking	Fluid escaping and dripping	**N/C**	Not checked

Disclaimer

This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal

This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.