Observation Report

Report No

Donington AUCTIONS & SALES

Auction Lot No
5

ABN: 21 625 963 475

LMCT: MCT-00412355 (VIC) - MD078801 (NSW)

Inspection Date	Make/Model	Year	Odometer - Mls / Km	VIN
24 November, 2026	Renault Floride	1961	55430mi	R1092-0042793

EXTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Presentation	✔					
Glass		✔				Some scratches
Bodywork	✔					
Paintwork	✔					
Lamps Condition		✔				
Bumper Bars		✔				Some dents & signs of previous repairs
Brightwork	✔					
Seals		✔				
Convertible Roof					✔	Soft top missing

INTERIOR	Good	Fair	Repair	N/C	N/A	Comments
Boot Area	✔					
Seats & Belts	✔					
Floor Coverings	✔					
Headlining/Visors	✔					
Trim		✔				
Doors	✔					
Windows and Mirrors		✔				
Heating and Ventilation		✔				
Lights/Wipers/Washers/Horn			✔			Wipers & rear indicators n/w, licence plate light n/w
Other Electrical				✔		
Entertainment Equipment					✔	
ABS/SRS					✔	

UNDERBODY	Good	Fair	Repair	N/C	N/A	Comments
Structure	✔					
Corrosion	✔					
Powertrain		✔				
Exhaust		✔				Small holes evident
Brakes			✔			LHF brake n/w, handbrake doesn't engage
Wheels & Tyres		✔				Tyres dated 44-2019, whitewalls stained
Steering & Suspension		✔				
Fuel System			✔			Stale fuel
Fluid Leaks		✔				

ENGINE BAY	Good	Fair	Repair	N/C	N/A	Comments
Presentation		✔				
Fluid Levels/Condition			✔			Needs service
Cooling System		✔				
Power Steering					✔	

Electrical		✔				
Engine Running	✔					
Air Conditioning					✔	

ROAD TEST	Good	Fair	Repair	N/C	N/A	Comments
Engine Performance		✔				Hesitates under light throttle
Transmission	✔					
Noise and Vibration		✔				
Steering and Suspension		✔				
Braking			✔			LHF brake n/w, pulls to right
Clutch		✔				
Instruments		✔				

Key

Good	Operational or well presented at time of inspection	**U/S**	Unservicable
Fair	Commensurate for age of vehicle but has wear and tear	**N/S**	Not secure
Repair	Requires repair, replacement or refurbishment	**N/W**	Not working
Wetting	Fluid escaping with the potential to drip	**N/A**	Not Applicable
Leaking	Fluid escaping and dripping	**N/C**	Not checked

Disclaimer

This is a visual inspection only carried out by Donington Auctions. No components are removed to aid in the inspection and any faults listed have not been conclusively diagnosed. Road tests are conducted on local roads of speeds up to 60Km/h. The vehicle underbody was visually inspected on a vehicle hoist. Donington will not be held liable or responsible in regards to any claim(s) in relation to this report or any implied influence to your decision to purchase the vehicle.

The following items are not included in this inspection report : - Engine Compressions, inspection of Cam/Timing Belt(s) or any internal

This observation report is not a substitute for a roadworthy certificate and in no way implies the vehicle will or will not pass a roadworthy inspection.